

0044

**KAISER
STEEL**

KAISER STEEL CORPORATION
WESTERN COAL OPERATIONS
SUNNYSIDE, UTAH 84539
TELEPHONE 801-888-4421

11 May 1982

File
ACT/007/007
Copy to Joe &
Jean & Jack

JIM

MAY 12 1982

Mr. Ronald Daniels, Dep Dir.
Division of Oil, Gas & Mining
4241 State Office Bldg.
Salt Lake City, Utah, 84114


re: So. Berm Outslope Pond
Sunnyside Mines
ACT/007/007

Dear Ron,

Concerning the South Berm Outslope Pond and its setting at the head of the Icelander Wash drainage, your comments are greatly appreciated. Thank you for your on-site visit on 5-6-82 and our phone conversation of 5-7-82. We concur that it would be unfortunate to have this pond removed because of the time and money spent, and its contribution to the environment. Therefore, since there is no new disturbed area above the pond and the old existing disturbance seems to be stabilized, Kaiser Steel Corporation requests that this pond be removed from the records as a sediment pond, being no longer subject to Division/OSM regulations and inspections; and henceforth shall be known only as a wildlife, stockwatering pond.

If this arrangement is not acceptable, this pond shall be immediately destroyed. We hope to hear from you soon.

Sincerely,



John S. Huefner, PE.
Civil Engineer

cc: Brett Harvey
Denise Drago

RECEIVED
MAY 12 1982

DIVISION OF
OIL, GAS & MINING