



0036
STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Scott M. Matheson, Governor
Temple A. Reynolds, Executive Director
Dr. G. A. (Jim) Shirazi, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

August 11, 1983

Mr. Douglas C. Pearce
Kaiser Steel Corporation
Western Coal Operations
P. O. Box D
Sunnyside, Utah 84539

RE: Review of the No. 2 Canyon
sediment
ACT/007/007, Folder No. 3
Carbon County, Utah

Dear Doug:

The following list of concerns must be addressed before the Division can grant approval for the No. 2 Canyon Pond. The concerns are as follows:

1. The amount of freeboard described in the ditch calculations is listed as .5 feet. This figure meets the .3 foot requirement listed under regulation UMC 817.43(f)(2). Although, on page 31 the freeboard for all ditches is listed as a minimum of .19 feet, this must be changed to reflect the .3 foot requirement.
2. The size of rip-rap used must be sufficient to prevent erosion and additional contributions of sediment from the conveyance of runoff.
3. The stipulations put forth in the Utah Department of Health approval letter must be adhered to.

Douglas C. Pearce
ACT/007/007
August 11, 1983
Page 2

4. Any topsoil encountered during excavation will be saved.

Thank you for your patience in the review of this structure.

Sincerely,



THOMAS MUNSON
RECLAMATION HYDROLOGIST

TM/jvb

cc: Tom Ehmett, OSM
Walt Swain, OSM
Steve McNeal, Dept. of Health
John Whitehead, DOGM
Steve Cox, DOGM
Bart Kale, DOGM