

0006

**KAISER
STEEL**

KAISER STEEL CORPORATION
SUNNYSIDE COAL MINES
SUNNYSIDE, UTAH 84539
TELEPHONE 801-888-4421

FILE ACT/007/007, #2

Copy to: Mary
Steve

To Mary
RECEIVED

SEP 4 1984

**DIVISION OF OIL
GAS & MINING**

August 31, 1984

Mr. James W. Smith, Jr.
Administrator MRD&RP
Division of Oil, Gas, & Mining
4241 State Office Building
Salt Lake City, Utah 84114

JIM
SEP 04 1984

Dear Mr. Smith:

RE: Additional Technical Deficiencies,
Kaiser Steel Corporation, Sunnyside
Mines, ACT/007/007, Carbon County,
Utah

Enclosed is a partial response to your letter of August 15, 1984. Additional material will be submitted to the Division as it becomes available. The areas that have not been completed are UMC 805.11, 817.43, 817.45, 817.46, 817.47, and 817.101, which involve the bond, hydrology calculations and methodologies, and outside consultation to determine the stability of highwalls and backfills.

A complete update of Chapter III and other affected areas will be submitted after all the above-mentioned areas have been completed. This should take less than two weeks from the receipt of this letter.

Sincerely,



Douglas C. Pearce
Mine Engineer

DCP:th

Enclosures