

September 5, 1984

TO: Memo to Coal File, Inspection and Enforcement  
FROM: Barton Kale, Mining Field Specialist *BOK*  
RE: Kaiser Steel Corporation, Sunnyside Complex, ACT/007/007,  
Folder #7, Carbon County, Utah

A partial inspection was conducted at the above mentioned mine site on August 13, 1984. The inspector was accompanied by Doug Pearce of Kaiser Steel Corporation.

The violation that was issued on discharge into II Canyon (NOV 84-6-9-1) was terminated at this time. The discharge was taken care of and no water was flowing at this time. Mr. Pearce claims that the valve that caused the problem was fixed in such a way as to not cause a problem again. The mine water discharge was sent back to its original point.

The strawbales have been fixed at the manshaft area. This action was requested during the previous inspection.

The sediment pond at the storage yard has received recent maintenance. The discharge standpipe has been attached in the proper fashion.

The excavation of the man shaft mine water pond is just about complete. The inflow and discharge points are still awaiting construction.

Temporary sealing of inactive portals and water data monitoring reports to the Division were discussed with the operator. At this time Kaiser Steel is aware of their responsibilities in these areas.

re

cc: D. Griffin, Office of Surface Mining  
Doug Pearce, Kaiser Steel Corp.  
P.O. Box D, Sunnyside, UT 84539  
Mary Boucek  
Joe Helfrich

Statistics:

Vehicle: 45428 X 425 miles  
Per Diem: 1 person X 2 days, 6 hours = \$92.00  
Grant: A&E  
00380 -6