



0009

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

ACT/007/007
#2

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

August 18, 1987

Mr. Barry Grosely
Mine Engineer
Kaiser Coal Corporation
P. O. Box 10
Sunnyside, Utah 84539

Dear Mr. Grosley:

Re: Repair of Storm Damage, Kaiser Coal Corporation, Sunnyside Mine, ACT/007/007, Folder #2, Carbon County, Utah

Division personnel Jim Fricke and Bill Malencik performed a complete inspection of the Sunnyside Mine site on August 11, 1987. During the inspection, extensive damage from a severe thunderstorm was observed by yourself and the inspectors.

The Division has determined that the high-intensity short duration storm exceeded the design storm events for the Sunnyside property. However, Kaiser must repair the damage and render all structures functional by September 30, 1987.

Should any repair of the damage deviate from the original approval plan, appropriate as-built plans must be submitted to the Division. Please refer to the inspection report dated August 11, 1987 for all repair items to be addressed.

Sincerely,

James R. Fricke
Reclamation Hydrologist

djh
cc: J. Whitehead
B. Malencik
0799R/22