

0026

SRS, Inc.

Sunnyside Reclamation & Salvage, Inc.

P.O. Box 99 — Sunnyside, Utah 84539

RET/007/007 #5
Copy to Tom & Jeff

May 1, 1990

RECEIVED
MAY 04 1990
DIVISION OF
OIL, GAS & MINING

Ms. Pamela Grubaugh Littig
Permit Supervisor
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Pamela:

Re: Inspection Report For April 5, 1990, Inspection


On April 5, 1990, Jesse Kelley and Henry Sauer conducted a complete inspection of the Sunnyside Facilities. On April 30, 1990, Sunnyside Coal Company received an Inspection Report for that inspection.

Please be advised that under Item 4(C), it was the SSF Pond that was receiving mine water, after receiving permission from the Division of Oil, Gas & Mining and the Bureau of Water Pollution Control, and not the SSP Pond.

In addition, the water has been diverted from 014 SSF Sediment Pond Discharge to 015 Discharge. The 015 Discharge does not utilize a pond as indicated, and such a facility is not required by our UPDES Permit (see enclosure).

If you have any questions in regard to this matter, please feel free to contact me.

Sincerely,



Karl R. Houskeeper
Environmental Coordinator

KRH:th

Enclosure

cc: Bill Balaz

A. Definitions (Continued)

SUNNYSIDE RECLAMATION AND SALVAGE, INC.
SUMMARY OF UPDES DISCHARGE POINTS

<u>Outfall No.</u>	<u>Location</u>	<u>Facility Type</u>	<u>Use Frequency</u>	<u>Treatment</u>
001	Manshaft shaft	Mine water discharge	Normally	Settling pond
002A	Whitmore shaft	Mine water discharge	Normally	Settling pond
002B	Whitmore shaft	Mine water discharge	Normally	Settling pond
003	No. 1 Mine portal	Mine water discharge	Infrequent	None
005	No. 2 Mine portal	Mine water discharge	Infrequent	None
006	Manshaft pond	Sediment pond	Runoff	None
010	Lower #2 canyon	Sediment pond	Runoff	None
011	Upper #2 canyon	Sediment pond	Runoff	None
013	#3 hoist house	Sediment pond	Runoff	None
014	Surface facilities	Sediment pond	Not yet built	None
015	#2 canyon (tanks)	Mine water discharge	Normally	None

Amended 12/1/89