

0039

ACT 10071007

mine bit CB



United States Department of the Interior

3046
(U-066)

BUREAU OF LAND MANAGEMENT

RECEIVED
FEB 12 1990

DIVISION OF
OIL, GAS & MINING

Moab District
Price River Resource Area
900 North 700 East
Price, Utah 84501

FEB 6 1990

State of Utah
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Sirs:

This letter is in regard to the December 18, 1989, Sunnyside reclamation and salvage oil spill.

Our office would like prompt notification of any future oil spills and the corrective actions required. Of particular concern is the recurrent nature of this problem, especially during the last year. Although federal land has not been directly affected, Grassy Trail Creek does provide water for both livestock and wildlife on federal land. Failure to control the pollutants means that they are likely to end up on federal lands and could affect water quality. At this time, this office has not been notified of any actions to permanently solve this problem. We would appreciate being included in the network for all unlawful discharges and the solutions proposed.

Thank you.

Sincerely yours,

Mark E. Bailey
Area Manager