


0047

Sunnyside Coal Company



Operations • Highway 123 • P.O. Box 99 • Sunnyside, Utah 84539

May 17, 1991

*Copy Henry, Pam
File per 7/007/007 #5*

Ms. Pamela Grubaugh-Littig
Permit Supervisor
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Pamela:

Re: NOV #N91-32-2-1 Deficiencies

Complete and adequate approval plans to fulfill the requirements of R614-301-746.212 are contained in Sunnyside Coal Company's approved Permit Act 007/007.

In response to the Division's letter dated May 7, 1991, outlining deficiencies to the abatement of NOV #91-32-2-1, Sunnyside Coal Company has revised Drawing No. D4-0174 to show further clarification of the approved drainage plan for the coarse refuse site.

More specifically, the Division noted a "significant discrepancy... between Plate III-6, C4-0058 and Plate D4-0174." The Division memo indicates a drainage path along the north side of the refuse area. Drainage from the north side of the area is conducted across each terrace of the refuse pile to the south side of the refuse area. The only drainage that remains on the north side of the refuse area is from the bottom slope beneath the last terrace at the base of the refuse area. This drainage then goes to the new CRT pond.

The remaining drainage above this point, as stated, all goes to the south side of the refuse area and then reports to the Railcut Pond. A concrete culvert was designed to be installed on the south side of the refuse area during final reclamation of the refuse area. The concrete culvert was not indicated on Plate D4-0174 because it is not in place at the present time; however, Sunnyside Coal Company has indicated the approximate location of the concrete culvert on Plate D4-0174 to avoid any confusion.

Corporate Offices
The Registry
1113 Spruce Street
Boulder, CO 80302
303-938-1506
FAX: 303-938-5050

Sales Office
1350 17th Street
Suite 350
Denver, CO 80202
303-534-3348
FAX: 303-825-8626

West Coast Division
1345 Astoria Drive
Fairfield, CA 94533
707-425-4506

Operations
Highway 123
P.O. Box 99
Sunnyside, UT 84539
801-888-4421
FAX: 801-888-2581

Ms. Pamela Grubaugh-Littig
Page 2
May 17, 1991

In an effort to abate NOV #91-32-2-1, Sunnyside Coal Company has also enclosed prints of Plate III-5, C4-0006; Plate III-6, D4-0080; and Plate III-6, D4-0079. The Division memo indicated these maps as either missing or as being revised after the Division stamp.

If any further information is needed to abate NOV #91-32-2-1, please contact me. If the Division feels that a conference is necessary to explain the drainage plans, then contact Sunnyside Coal for scheduling.

Sincerely,



Karl R. Houskeeper
Environmental Coordinator

KRH:th

Enclosures

cc: Joe Fielder
Gary Gray