

0021

January 30, 1985

TO: Coal File, Inspection and Enforcement
FROM: Barton Kale, Mining Field Specialist *BOX*
RE: U. S. Fuel Company, Hiawatha Complex, ACT/007/011, Carbon
County, Utah

A partial inspection was conducted at the above mentioned mine site on January 24, 1985 by Barton Kale of the Division. The inspector was accompanied by Jean Semborski of U. S. Fuel.

The inlet to the sediment pond in the middle fork canyon was open and should receive runoff during any melting situation. The inlets to the sediment pond in the south fork canyon needed maintenance. The operator was informed that this area would be watched during future inspections.

The operator was also informed of the notification of State Health in relation to the potential TDS problem at the Morland discharge point (see January 14, 1985 memo). Mr. Steve McNeal of State contacted the inspector and discussed the matter. The resolution of the problem by State Health would involve changing the limitation on a quarterly basis (raising them) and putting a limit (in pounds) on yearly discharge of TDS.

wj
cc: Jean Semborski, U. S. Fuel
Donna Griffin, OSM
Joe Helfrich, DOGM

Statistics:

Vehicle: 5429 x 423 miles
Per Diem: 1 person x 1 day, 6 hours = \$50
Grant: A & E

0068Q-14