

0032



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

RECEIVED
JAN 28 1991
CLERK OF COURTS
JG

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

PERMIT NO.: ACT/007/011
Inspection Date: January 16, 1991

Permittee and/or Operators Name: U.S. Fuel Company
Business Address: P.O. Box A
City: Hiawatha State: Utah Zip: 84527
Mine Name: Hiawatha Complex County: Carbon State: Utah
Type of Mining Activity: Underground Surface Other
Company Official (s): Bob Eccli
State Officials (s): Stephen J. Demczak
Time of Inspection: 8:30 a.m. p.m. to 11:30 a.m. p.m.
Partial Complete: Date of Last Inspection: Dec. 20, 1990
Weather Conditions: Warm/Sunny/6" Snow
Acreage: Permitted 20,700 Disturbed 290 Regraded Seeded
Bonded 290 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	(X)	()	()	(X)
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	(X)
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/011 INSPECTION DATE January 16, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

c. Sediment Ponds And Impoundments:

Inspected sediment ponds, no problems noted. Most ponds were snow covered. Ponds were not discharging.

d. Other Sediment Control Measures:

All control measures observed were intact and functioning properly.

5. EXPLOSIVES:

Explosives outside storage container were locked and properly grounded.

17. OTHER TRANSPORTATION FACILITIES:

The Moreland pipeline was functioning properly. No water leaks were observed.

Copy of report:

Mailed to: Bob Eccli (USFC)

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39 Date: 1/16/91

Stephen J. Demczak