

007/011 #2

0001

UNITED STATES FUEL COMPANY

BOX 887
PRICE, UTAH 85401



(801) 637-2252
FAX (801) 343-2344

November 10, 1992

RECEIVED

NOV 13 1992

DIVISION OF
OIL GAS & MINING

Daron Haddock, Permit Supervisor
Division of Oil, Gas and Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: Mining and Reclamation Permit Submittal, U. S. Fuel Company,
Hiawatha Mines Complex, ACT/007/011

Dear Daron:

Enclosed is a summary of U.S. Fuel's responses to the mid-term Technical Deficiency Review of March 4, 1992. The summary lists the responses in the same order as the deficiencies were listed in the review. This should help to locate where each deficiency is addressed in the permit.

After the revised permit volumes were shipped to your office it was found that Exhibit V-13C had not been certified, therefore, I have enclosed 13 certified copies.

Please note that U.S. Fuel's mailing address has changed. The old address was Box A, Hiawatha, Utah 84527. The new address is P.O. Box 887, Price, Utah 84501. Also, there have been some changes in names and titles of corporate officers so I have enclosed revised copies of pages 1 and 2 of Chapter I.

Sincerely,

Robert Eccli
Sr. Mining Engineer