

# Hiawatha Coal Company

P.O. Box 1202  
Huntington, UT 84528

(435) 637-1778  
FAX (435) 637-1378

November 25, 1998

Coal Program  
Utah Division of Oil, Gas & Mining  
1594 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, Utah 84114-5801

To Whom It May Concern,

*Copy Cover to*

Re: Water Monitoring Report, 3rd Quarter, 1998. Hiawatha Coal Company.  
Hiawatha Complex, ACT/007/011, Carbon County, Utah

#7

*Ken; Paul*

Enclosed is the Water Monitoring Report for the 3rd Quarter of 1998.

We apologize for the delay in submitting the 3rd Quarter Water Monitoring report. We were waiting on the lab analysis for ST-3. The results of the analysis showed a Cations/Anions balance which was approximately 31% off. We were unable to identify the cause of the imbalance, other than a bad sample. HCC has collected another sample and is currently awaiting the results from the lab. As soon as the results are received, they will be forwarded to the Division.

If you have any questions, please call me at (435) 637-1778.

Sincerely,



Charles Reynolds, PE  
Mining Engineer


Enclosure (s)  
CR/ho

# Hiawatha Coal Company

P.O. Box 1202  
Huntington, UT 84528

(435) 637-1778  
FAX (435) 637-1378

Coal Program  
Utah Division of Oil, Gas & Mining  
1594 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, Utah 84114-5801



August 6, 1998

To Whom It May Concern,

Re: Water Monitoring Report, 2nd Quarter, 1988. Hiawatha Coal Company,  
Hiawatha Complex, ACT/007/011, Carbon County, Utah

5.1  
#7

Enclosed is the Water Monitoring Report for the 2nd Quarter of 1988.

If you have any questions, please call me at (435) 637-1778.

Sincerely,

Charles Reynolds, PE  
Mining Engineer


Enclosure (s)  
CR/ho

# Hiawatha Coal Company

P.O. Box 1202  
Huntington, UT 84528

(435) 637-1778  
FAX (435) 637-1378

Coal Program  
Utah Division of Oil, Gas & Mining  
1594 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, Utah 84114-5801



April 28, 1998

To Whom It May Concern,

Re: Water Monitoring Report, 1<sup>st</sup> Quarter 1998, Hiawatha Coal Company,  
Hiawatha Complex, ACT/007/011, Carbon County, Utah

# 7

Enclosed is the Water Monitoring Report for the 1<sup>st</sup> Quarter of 1998.

If you have any questions, please call me at (435) 637-1778.

Sincerely,

A handwritten signature in cursive script that reads "Charles Reynolds".

Charles Reynolds, PE  
Mining Engineer

HIAWATHA COAL COMPANY, INC.

P.O. Box 1202

Huntington, Utah 84528

Phone (435) 637-1778 Fax (435) 637-1378

January 27, 1998

Coal Program  
Utah Division of Oil, Gas & Mining  
1594 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, Utah 84114-5801

To Whom It May Concern,

Re: Water Monitoring Report, 4th Quarter, 1997, Hiawatha Coal Company, Hiawatha Complex, ACT/007/011, Carbon County, Utah

# 7

Enclosed is the Water Monitoring Report for the 4<sup>th</sup> Quarter of 1997.


If you have any questions, please call me at (435) 637-1778

Thank You,

*E. O. Finley*

Elliot Finley,  
Resident Agent

Enclosure (s)





9 17 98

A CT/007/011

Higwatha

Topsoil Borrow area A



ACT/007/011

Hiawatha

Slurry Pond 4



9 17 98

ACT/002/011

Hiawatha

Topsoil borrow area A  
lots of weeds.



ACT/002/011

Hiawatha

Ditch northeast of  
pond 4 needs to  
be fixed -



8/23/98

ACT/007/011

Hiawatha

pond 4 re vegetation -

lots of grasses, few weeds  
or shrubs.



ACT/007/011 Hiawatha

Removing coal fines from  
area northeast of slurry  
pond 4

---

ACT/007/011  
Hiawatha

Top of slurry pond 5



ACT/007/011

Hiawatha

slurry pond 4

---

ACT/007/011 Hiawatha

Removing coal fines from  
area northeast of slurry  
pond 4.