

**OGMCOAL - Re: Fwd: Utah Railway contact info?**

---

**From:** April Abate  
**To:** Mark Reynolds; Steve Demczak  
**Date:** 1/5/2010 8:53 AM  
**Subject:** Re: Fwd: Utah Railway contact info?  
**CC:** OGMCOAL@utah.gov; Steve Demczak  
**Attachments:** DSCN3288.JPG; DSCN3289.JPG; April Abate.vcf

---

Mark,

The problem is with the berm and not so much with the catch basin that you addressed in your response. I understand that it is on the ROW, but Hiawatha has made attempts to repair the berm in the past. Why not just try to do the right thing and keep up with it and keep the coal fines from migrating off the disturbed area? Here are some of the photos I took of the conditions of the berm during the midterm inspection.

The people here are just trying to do our jobs and do the right thing for these sites. I was pretty disappointed by the tone of your email. I really hope you and Hiawatha will make a better effort to work with us. More and more it seems to me that for every step forward we take, we end up taking two steps back.

**April A. Abate**

*Environmental Scientist II*

Division of Oil, Gas and Mining  
1594 W. North Temple, Suite 1210  
Salt Lake City, Utah 84114-5801

*T: 801.538.5214*

*F: 801.359.3940*

*M: 801.232.1339*

>>> Steve Demczak 1/5/2010 6:15 AM >>>



