

Document Information Form

Mine Number: C1007/012

File Name: Internal

To: DOGM

From:

Person N/A

Company OFFICE OF SURFACE MINING RECLAMATION AND ENFORCEMENT

Date Sent: AUGUST 20, 1984

Explanation:

TEN-DAY NOTICE.

cc:

File in:
C/ _____, _____, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

cc: RW DANIELS
JOE HELFRICH

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office:
Office of Surface Mining
219 Central, NW #216
Albuquerque, NM 87102
Telephone Number: 505 766-1486

Number: X-84-2-212-2 TV 1

Ten-Day Notice to the State of Utah

You are notified that, as a result of State inspection report of 6-5-84 (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: US Steel Corporation County: Carbon Surface
(Or Operator if No Permit)
Mailing Address: PO Box AE Paonia CO 81428 Underground
Permit Number: ACT 1007/012 Mine Name: Wellington Prep Plant Other Prep Plant

NATURE OF VIOLATION AND LOCATION: UMC 817.45 (i) + (iii) Failure to design, construct + maintain appropriate sediment control measures to prevent, to the extent possible, additional contributions of sediment to streamflow
Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: and to minimize erosion to the extent possible. This applies to water discharged from the slurry pipeline which was handled with an inadequate catch basin. The basin
Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: Boiled + discharged silt laden water directly into the Price River.
Section of State Law, Regulation or Permit Condition believed to have been violated:

RECEIVED

Remarks or Recommendations: _____

AUG 20 1984

Date of Notice: 8-15-84

Signature of Author _____
Print Name and ID: _____

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No. 0007 Date _____
In C/ 007, 012, Internal
For additional information _____

F O I L
I N G.

cc: RW Daniels
Joe Helfrich

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office: Office of Surface Mining
219 Central, NW #216
Albuquerque, NM 87102
Telephone Number: 505 766-1486

Number: X-84-2-242-2 TV 1

Ten-Day Notice to the State of Utah

You are notified that, as a result of State inspection report of 6-5-84 (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: US Steel Corporation County: Carbon Surface
(Or Operator if No Permit)
Mailing Address: PO Box AE Paonia CO 81428 Underground
Permit Number: ACT 1007/012 Mine Name: Wellington Prep Plant Other Prep Plant

NATURE OF VIOLATION AND LOCATION: UMC 817.45(1)+(iii) Failure to design, construct & maintain appropriate sediment control measures to prevent, to the extent possible, additional contributions of sediment to streamflow
Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: and to minimize erosion to the extent possible. This applies to water discharged from the slurry pipeline which was handled with an inadequate catch basin. The basin
Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: Boiled & discharged silt laden water directly into the Price River.
Section of State Law, Regulation or Permit Condition believed to have been violated:

RECEIVED

Remarks or Recommendations: _____
AUG 20 1984

DIVISION OF OIL
GAS & MINING.

Date of Notice: 8-15-84 Signature of Authorized Rep: Jodie Merriman
Print Name and ID: Jodie Merriman 242