

0002



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter  
Governor

Dee G. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

August 19, 1988

TO: File

FROM: Susan C. Linner, <sup>SCL</sup> Reclamation Biologist/Permit Supervisor

RE: Review of Revised Chapter I, Kaiser Coal Company,  
Wellington Preparation Plant, ACT/007/012, Folder #2,  
Carbon County, Utah

## Summary

A revised Chapter I was received for the Mining and Reclamation Plan (MRP) for the Wellington Prep Plant on July 15, 1988. This is in partial fulfillment of stipulation UMC 788.14-(1)-SCL to the Mid-Term Permit Review approval. This chapter was reviewed for completeness and adequacy.

## Analysis

The following sections were found to be incomplete. Submittal of information as outlined in the comments will be necessary before Chapter I can be accepted as replacement for existing Chapter I.

### UMC 782.13 Identification of Interests - SCL

- (e) Page 6 needs to be revised to include an address for Merrill and Ellen Mead, shown as owners on drawing C4-0077.

The address listed for the Utah Division of State Lands and Forestry is incorrect.

- (g) This section was not addressed.

### UMC 782.15 Right of Entry and Operation Information - SCL

A copy of the Purchase and Sale Agreement must be included.

Page 2  
Review Revised Chapter 1  
Kaiser Coal Corporation

UMC 782.18 Personal Injury and Property Damage Insurance  
Information - SCL

A copy of the current Certificate of Insurance must be included.

UMC 782.19 Identification of Other Licenses and Permits - SCL

Section 1.2.7 should reference a permit from the Division of Water Rights (State Engineer's Office) for the slurry ponds. Information on water rights should also be included.

UMC 786.19 Criteria for Permit Approval or Denial - SCL

(k), (l), (m), (o) Section 1.4.2 should reference the appropriate sections of the MRP where information required by these subsections is contained.

Recommendation

Although Chapter I as submitted is deficient, it is recommended that no action be taken at this time due to the fact that the property may be sold in the next 30-45 days. A new owner would be required to submit a complete new Legal/Financial Section before permit transfer could occur.

If the property is not sold by October 1, 1988, it is recommended that these deficiencies be forwarded to Kaiser Coal Company.

SCL/cl  
cc: L. Braxton  
H. Sandbeck  
WPOB45/5-6