



OGMCOAL DNR &lt;ogmcoal@utah.gov&gt;

---

## Re: Selenium Concerns at Wellington Prep Plant Addressed

---

**Steve Christensen** <stevechristensen@utah.gov>

Thu, Sep 29, 2016 at 11:05 AM

To: Patrick Collins <mt.nebo@xmission.com>

Cc: "Timothy P. Stanley" <tpstanley@g1hi.com>, OGMCOAL DNR <ogmcoal@utah.gov>

Good morning Pat,

Sorry for not getting back to you sooner on this. I appreciate all the work that you and Erik put in to getting to the bottom of the elevated selenium issue.

I've had a chance to look at the report and I'm glad that it was nothing more than a lab error. Over the coming weeks/months, I'll go into the database and input the re-run selenium concentrations by hand. I'll chip away at it as time allows.

One thing I wanted to mention, and we've discussed this before, we need to update the MRP with an up to date list of the required monitoring sites. It'd be a quick and easy amendment. Reason being, there are sites in the MRP that are no longer monitored (e.g. GW-12 and GW-11). If you could put an up to date table together of the surface and ground water monitoring sites, it'd help a lot in cleaning up the MRP and what's required/what's not. It'd literally be a two page amendment. Give me a call and we can discuss it.

Thanks again Pat.  
Steve

On Tue, Sep 6, 2016 at 1:42 PM, Patrick Collins <mt.nebo@xmission.com> wrote:

Hello Steve:

Attached is a letter-report that addresses your questions about Se at the Wellington site. Also attached are the revised lab analysis reports. I tried to combine the lab data into a single more manageable file but the lab evidently adds an extra layer of protection to their pdf files that prevents changing them in any way.

Let me know that you received this document and if we have adequately addressed your concerns.

Patrick D. Collins, Ph.D.  
Mt. Nebo Scientific, Inc.  
*Research & Consulting*  
330 East 400 South, Suite 6  
Springville, Utah 84663

ph. (801) 489-6937

—  
Steve Christensen  
Utah Division of Oil, Gas and Mining  
1594 W North Temple, Suite 1210  
Salt Lake City, Utah 84116  
(801) 538-5350  
stevechristensen@utah.gov