

0015

Internal
00070013
Task 0573

From: Priscilla Burton
To: Grubaugh-Littig, Pam; Wayne Hedberg
Date: 8/28/2006 2:20:44 PM
Subject: Task 2573 Phase III bond Horse Cyn

All,

I met with the Emery Co. Road Supervisor (Morris Sorenson) and two Emery Co. Commissioners (Hatch and Kofford) and Ray Peterson (Public Lands Council, formerly Road Supervisor). They looked at the bridge and decided that one abutment (downstream/west side) should stay since it is serving to support the embankment and one abutment (upstream/east side) should be removed, since is posed a hazard to the bridge, should it topple over due to erosion. (see attached photos).

Second item of discussion is the problem of fencing along the length of the County Road, which makes it impossible for the County to keep ditches clear and control road erosion. They request the road fencing be removed. (see attached photos).

DOGM also stressed removing all fences in our Phase III bond release field visit (4/13/06), but as of today, no action had been taken by UEI on either removing fences or removing the metal fan portal housing left by the buildings.

I will include the above in my memo for the task due 9/15/06, but wonder if we should relate these issues to Jay either in a letter or telephone call.

Priscilla Burton
Certified Professional Soil Scientist
Utah Division of Oil Gas & Mining
Price Field Office
455 West Rail Road Ave.
Price UT 84501

priscillaburton@utah.gov
(435) 613-1146 x 207

CC: Wayne Western



