

Outgoing
C0070013

#3408
K



Action Taken on Existing Citation Utah Coal Regulatory Program

1594 West North Temple, Salt Lake City, UT 84114
Phone: (801) 538 - 5285 Fax: (801) 359-3940

Action on Citation#: **10045**

Permit Number: **C0070013**

Date Cit. Issued: **9/23/2009**

MODIFICATION of

TERMINATION of

VACATION of

NOTICE OF VIOLATION

CESSATION ORDER (CO)

FAILURE TO ABATE CO

Permittee Name: UtahAmerican Energy Inc.

Inspector Number and ID: **37** **PBURTON**

Mine Name: Horse Canyon Mine

Date and Time of Action: **04/12/2010**

Certified Return Receipt Number:

Date and Time of Service: **04/12/2010**

*In accordance with the provisions of the Utah Coal Mining and Reclamation Act,
Utah Code Ann. § 40-10-1 et. seq. (Act), the above referenced Citation is:*

Modified as follows:

Reason for modification:

Terminated because:

Sediment control has been maintained. Signs have been placed. An amendment to the MRP (Task 3498) was received March 11, 2009 and reviewed (Internal documents 03242010 (soils) and 04052010 (engineering). [Final approval is pending resolution of unrelated deficiencies (Outgoing 04062010).] A draft Topsoil Movement Record was provided that describes the volume of soil salvaged in Phase 1. The final copy (to be filed with the annual report) will use Plate 1-1 to calculate the acreage remaining to be salvaged in Phase 2 (per Jay Marshall 3/29/2010). Subsoil protection and monitoring have been revised in Section 241 to accommodate the new design.

Vacated because:

JAY MARSHALL

(Print) Permittee Representative

PRISCILLA BURTON

(Print) DOGM Representative

Permittee Representative's Signature - Date

Priscilla Burton **4/12/2010**
DOGM Representative's Signature - Date

Refer to the "Citation For Non-Compliance" for additional information