

UtahAmerican Energy, Inc.



Lila Canyon Project
P. O. Box 910
East Carbon, Utah 84501
Phone: (435) 888-4000
(435) 650-3157
Fax: (435) 888-4002

*C/002/013 Incoming
map Confidential*

July 22, 2014

Daron Haddock
Permit Supervisor
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

TASK ID# 4551

Re: UtahAmerican Energy, Inc. Lila Canyon Mine, ACT/009-013, (2013 Annual Report)
(L14-001) Additional Information Requested.

Dear Mr. Haddock:

Please find attached UEI's response to DOGM's request for additional information to the 2013 Annual Report.

Item #1

During the 2013 midterm review, the vegetation success of the test plot was evaluated and recommendations were provided to the permittee with regard to seeding and weed control.

Attached is a PO listing the work that was done according to DOGM's requests at the midterm review. Note that the topsoil pile was reshaped, mulched and reseeded. The areas adjacent was scarified mulched and reseeded.

Item #2

The confidential portion of the annual report only includes a raptor survey map. A map showing the current and 5yr mining projection needs to be provided in the annual report. Map 5-3 needs to be updated.

A new revised Plate 5-3 (CONFIDENTIAL) showing 5 yr mining projection is attached for inclusion in the annual report.

If you have any questions please give me a call.

Sincerely,

A handwritten signature in black ink that reads "R. Jay Marshall".

R. Jay Marshall P.E.
Project Manager / Chief Engineer
Lila Canyon Mine

RECEIVED

JUL 25 2014

DIV. OF OIL, GAS & MINING

**UTAHAMERICAN ENERGY-LILA
PURCHASE REQUISITION**

M13-058

REQ NUMBER

REQUESTED BY: <i>R. Jay Marshall</i>	USED ON: Lila	SHIP TO: Lila	DATE: 11/18/2013
---	------------------	------------------	---------------------

VENDOR NAME Scamp Excavation	REQUIRED DATE	PURCHASE ORDER	FOB	TERMS	VIA	COMMENTS
---------------------------------	---------------	----------------	-----	-------	-----	----------

LINE ITEM	QTY REQ	PART NUMBER	DESCRIPTION	MANUFACTURER	INVENTORY CODE	BUDGET NUMBER	ACCOUNT NUMBER	UNIT PRICE	EXTENDED AMOUNT	TAX E
1	1		Perform work identified during the Mid-Term Inspection					\$12,500.00	\$12,500.00	
2			Includes: 1) Reshaping South end of topsoil pile						\$0.00	
3			2) Pocking topsoil pile similar to North Side						\$0.00	
4			3) Hay Straw Mulch reshaped topsoil pile						\$0.00	
5			4) Scarify area north of topsoil pile						\$0.00	
6			5) Re-seed both reshaped topsoil pile and area to North						\$0.00	
7			Includes seed and mulch						\$0.00	
8			6) Reestablish road and burm around topsoil pile						\$0.00	
9									\$0.00	
10			Any other Misc work discussed at Mid-Term						\$0.00	
11			Review that was attended by Scamp						\$0.00	
12									\$0.00	
TOTAL:									\$12,500.00	

MINE MANAGER APPROVAL: R. Jay Marshall	DATE 11/18/2013
PRESIDENT'S APPROVAL:	DATE
EVP / CFO APPROVAL:	DATE

PURCHASING AGENT'S APPROVAL:	DATE
VP OF OPERATIONS APPROVAL:	DATE
DIRECTOR / CEO APPROVAL:	DATE