

0015



United States Department of the Interior  
OFFICE OF SURFACE MINING  
Reclamation and Enforcement  
POST OFFICE BLDG. RM. 270  
1823 STOUT STREET  
DENVER, COLORADO 80202

OFFICE OF THE REGIONAL DIRECTOR



▶ 1 JUN 1979

Mr. Ron Daniels  
Staff Assistant  
Division of Oil, Gas, and  
Mining  
Dept. of Natural Resources  
1588 West North Temple  
Salt Lake City, Utah 84416

Dear Ron:

Reference: Braztah #3 Mine Water Monitoring Wells

Attached is an additional requirement of the Department for the  
Braztah #3 Mine. Please ensure that this requirement is included  
in any approval of the proposed water monitoring well operations.

Sincerely,

DONALD A. CRANE

Attachment



# United States Department of the Interior

## GEOLOGICAL SURVEY

Office of the Area Mining Supervisor  
Conservation Division  
8426 Federal Building  
125 South State Street  
Salt Lake City, Utah 84138

May 11, 1979



Memorandum

To: Regional Director, Office Surface Mining, Denver

From: Area Mining Supervisor, WRMA

Subject: American Electric Power, Braztah No. 3  
Mine, Water Monitoring Well

We have been contacted by both the State and OSM on the subject monitoring well and have no objection to the proposed well provided the coal seams are adequately protected by cementing through the coal seams, 50 feet above and below each coal seam. If the hole bottoms less than 50 feet below a coal seam, cementing from the bottom of the hole to 50 feet above the seam will be acceptable.

We also want to inspect the core above the coal seams to obtain information on roof conditions.

*Jackson W. Moffitt*  
For Jackson W. Moffitt

