

0006



SCOTT M. MATHESON
Governor

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

CLEON B. FEIGHT
Director

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS, AND MINING
1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

OIL, GAS, AND MINING BOARD

CHARLES R. HENDERSON
Chairman

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
CONSTANCE K. LUNDBERG
EDWARD T. BECK
E. STEELE McINTYRE

August 21, 1979

Mr. Movell Jewkes
730 North 4th East
Price, Utah 84501

RE: ACT/007/016

Dear Mr. Jewkes:

On August 16, Jim Smith and I met with representatives of Swisher Coal Company concerning the springs located on your property.

Three main entries were developed under your property between the dates of November 25, 1975 to January 3, 1976. The springs were probably undermined in the early part of that period. Support pillars were pulled and Swisher retreated from under your property during the period of June and July, 1977. The section was sealed off March 17, 1978. Two major faults are shown on the mine development map that occur on two sides of the springs you are concerned with. The faults do not outcrop on the surface in the location of the springs.

Swisher agrees to monitor the developed spring and the adjacent spring on a monthly frequency for flow quantity and water quality when snow conditions permit. This step is absolutely necessary to protect your resource. To do so Swisher will need your cooperation for access on the property. The monitoring program is necessary to document long term conditions of the spring. The Division will also spot check the results to assure the monitoring program results are accurate.

If you have any questions please contact Tom Suchoski or myself.

Sincerely,

K. MICHAEL THOMPSON
ENGINEERING GEOLOGIST

cc: Dan Guy, Swisher Coal Co.
Larry Damrau, Office of Surface Mining

KMT/te