

0006

BEAVER CREEK Coal Company  
P. O. Box AU  
Price, Utah 84501  
Telephone 801 637-5050

File ACT/007  
Copy to Steve, Tom & Dave D.  
w/a map.

June 18, 1982

JIM

JUN 22 1982

Mr. James W. Smith  
Coordinator of Mined Land Development  
Division of Oil, Gas & Mining  
4241 State Office Building  
Salt Lake City, Utah 84114

Re: #2 MINE YARD RENOVATION

Dear Jim:

Please find enclosed three (3) copies of our proposed #2 Mine Yard Renovation. I hope this will be adequate to expedite the approval since the work is scheduled to begin on June 28, 1982. My apologies for not providing the map earlier, but some changes had to be made after the contractor on-site meeting this week. Please note that the additional culverts planned in the property are at or near the size of the sediment pond overflow culvert and, therefore, should be more than adequate to control the expected runoff.

If you have any questions concerning this plan, please call me.

Thank you for your cooperation.

Respectfully,

BEAVER CREEK COAL COMPANY



Dan W. Guy  
Engineering Manager

DWG/daf

Enclosures (3)

cc: File

1 copy - DAVE  
1 copy - Steve  
1 copy - file