

0014

August 18, 1983

Inspection Memo  
to Coal File:

RE: Beaver Creek Coal Company  
Gordon Creek #2 Mine  
ACT/007/016  
Carbon County, Utah

A partial inspection of the above mentioned mine site was conducted August 11, 1983 by Barton Kale of the Division, accompanied by Dan Guy of Beaver Creek Coal Company (BCCC). The purpose of the inspection was to review abatement procedures on violations issued during the previous two weeks.

The material behind the perimeter markers and draining to the road, will be regraded to drain to the pond. Excess materials that has sloughed to the road will be retrieved to the rest of the waste. Strawbales have been replaced in the road to provide temporary sediment control until grade work is finished. BCCC is working on determining the boundary of their permit area to find out if their sign was placed in an adequate location.

The truck fill-up area has received maintenance to the pad and berms. The truck water area is in the process of being addressed. The area will be filled with drain rock, with a berm built up to prevent free flowing water from entering the pond. A more permanent solution will be to put rock gabions in front of the trucks.

*Barton Kale*  
BARTON KALE  
FIELD SPECIALIST

BK/jvb

cc: Tom Ehmett, OSM  
Dan Guy, BCCC  
Steve Cox, DOGM  
Joe Helfrich, DOGM

STATISTICS:

Vehicle: EX 45428 = 677 miles  
PerDiem: 2 days, 7.5 hours = \$91.36