

0057

Beaver Creek Coal Company  
P.O. Box AU  
Price, Utah 84501  
Telephone 801 637-5050

RECEIVED  
MAR 14 1984



DIVISION OF  
OIL, GAS & MINING

March 12, 1984

Mr. Barton Kale  
Utah Division of Oil, Gas and Mining  
4241 State Office Building  
Salt Lake City, Utah 84114

Dear Mr. Kale:

As required for the abatement of violation No. N-94-6-3-1 Beaver Creek Coal Company hereby submits their commitment to stabilize the bank between the road leading to Sweets Canyon pump house and the channel modification in Gordon Creek. Per our discussion over the telephone the debris on the bank was removed and hauled to the Gordon Creek No. 3 Mine pad area for use during reclamation. The bank will be reseeded this spring using the Gordon Creek No. 2 Mine temporary seed mix.

If you have any questions regarding this commitment, please do not hesitate to contact me.

Sincerely,

Scott M. Raymond  
Senior Environmental Coordinator

SR/cn