



STATE OF UTAH

Notice of Violation No. N 85-8-5-1

Violation No. 1 of 1

Nature of the Violation

failure to prevent to the extent possible additional contributions
of sediment to stream flow or to runoff outside the permit area

Provision(s) of the Regulations, Act, or Permit Violated

UMC 817,45

UCA 40-10-18 (1) (i)

UMC 817,43 (c)

Portion of the Operation to which Notice Applies

1. Undisturbed diversion ditch # 1 pad between fan and sediment
pond
2. Undisturbed diversion ditch # 2 pad from coal stockpile to bathhouse

Remedial Action Required (including interim steps, if any)

1. Clean contamination out of undisturbed diversion
2. Submit plans to the Division for prevention of contamination of the
undisturbed drainage by the coal stockpile

Time for Abatement (including time for interim steps, if any)

No later than April 12, 1985