

0025

BEAVER CREEK Coal Company

Post Office Box 1070
Price, Utah 84501
Telephone 801-857-6171

file INA/007/017
#2



May 19, 1987

Mr. Lowell P. Braxton
Administrator
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RECEIVED
MAY 22 1987

**DIVISION OF
OIL, GAS & MINING**

Re: Sediment Pond Embankment
Stability and Stipulation
Response UMC 817.46 (1,2)
Gordon Creek #3/#6 Mines
INA/007/017 #2
Carbon County, Utah

Dear Mr. Braxton:

Enclosed are 15 copies of the Beaver Creek Coal Company response to Stipulation UMC 817.46 (1,2) as requested by Mr. John Whitehead in his letter of 4/16/87. Also included with this response is the stability analysis for the eastern embankment of the lower sediment pond, per your request of 4/20/87.

All pages and maps are numbered and should replace corresponding pages and plates in the plan.

If you have any questions, or need any further information, please let me know.

Respectfully,

Dan W. Guy
Manager Permitting/Compliance

DWG/rs

cc: R.J. Marshall
W.S. Wagener
File