

0031

BEAVER CREEK Coal Company

Post Office Box 1378
Price, Utah 84501
Telephone 801 637-5050



February 24, 1988

Mr. Lowell P. Braxton
Administrator
Utah Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RE: Mid Term Review Defeciciencies
Gordon Creek No. 2 and 7 Mines
ACT/007/016, #2
Carbon County, Utah

Dear Mr. Braxton:

Enclosed are three copies of the Beaver Creek Coal Company response to the No. 2 and 7 Mine Mid-Term Deficiency comments of 1/11/88. Also enclosed is a reviewer checklist for response locations.

All pages and plates are numbered, and should replace corresponding numbers in the previously submitted plan. Please note that a new section - "Reclamation-Hydrology" - has been included with this submittal, and should be added to Chapter 7 of the plan.

If you need anything further, please let me know.

Respectfully,

Dan W. Guy
Manager Permitting/Compliance

cc: Johnny Coffey
Jay Marshall
Allen Childs
File

RECEIVED
FEB 26 1988

DIVISION OF
OIL, GAS & MINING