

0002



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 11/26/91 - 8:20 am to 10:15 am

Permittee and/or Operator's Name: Mountain Coal Co.
Business Address: P. O. Box 1378, Price, UT 84501; (801) 637-5050
Mine Name: Gordon Creek #2, #7 & #8 Permit Number: ACT/007/016
Type of Mining Activity: Underground Surface Other
County: Carbon County Company Official(s): Dan Guy
State Officials(s): Ken Wyatt, Susan White
Federal Official(s): None
Partial: Complete Date of last Inspection: 10/16-17/91
Weather Conditions: Cloudy, cold, incoming storm
Acreage: Permitted 2289 Disturbed 17.2 Regraded 0
Seeded 0 Bonded 17.2 Enforcement Action: AVS check

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 1 of 2

PERMIT NUMBER: ACT/007/016

DATE OF INSPECTION: 11/26/91

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENT:

1. PERMITS

The mine plan at Mountain Coal Companies offices referenced Mountain Coal Company as the operator of the Gordon Creek 2,7 &8 Mine permitted as ACT/007/016. The permittee's address is P.O. Box 1378, Price Utah. The permit lists the main office phone number (637-5050) while the mine ID sign references the mine office at the Trail Mountain #9 mine. Both numbers are functional.

4b. HYDROLOGIC BALANCE: - DIVERSIONS

The flexible culvert on the outslope of the #8 mine pad had been replaced since the previous inspection.

4c. HYDROLOGIC BALANCE: - SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were containing water. Pond #2 was cleaned this year. No discharges were occurring.

4d. HYDROLOGIC BALANCE: - OTHER SEDIMENT CONTROL MEASURES

The straw bales along the haul road had been replaced.

Copies of this Report:

Mailed to: Bernie Freeman (OSM); Dan Guy (MCC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:  #7 Date: 11/26/91