

0004



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

H: Old Fan

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

*Copy to TA
notebook*

TO: Permit Supervisor
From: Tom Munson *[Signature]*
RE: N.O.V. #94-45-1-1, Review of Old Fan Portal BTCA,
Gordon Creek No. 2/7/8 Mines, Mountain Coal Co.,
INA/007/016-94E, Folder #5, Carbon County, Utah

Synopsis

On November 30, 1994 the Division received an abatement of N.O.V. #94-45-1-1. The portion of the review which this memo addresses is review of the submitted designs for the affected area, since it was felt that the operator's Sed Cad computer run failed to address all the areas identified in the Old Fan Portal Area.

Analysis

The operator has submitted plans to treat the area identified on Plate 3-2 with silt fence and the location of the silt fence is shown on this Plate. The operator has also calculated the amount of insignificant flow coming from this area, as well as, provided a SedCad coputer run on contributions of sediments leaving the area versus a comparison to undisturbed area sediments. The area is partially reclaimed according to the inspector and other Division personnel. This is the reasoning behind the need for treatment of additional contributions of suspended sediment leaving this small area.

Recommendation

The Nov be terminated based on the fact that the operator has provided all the neccessary items to abate the Violation and has provided sediment control and designs to treat the Old Fan Portal Area.

