



Suzanne Steab <suzannesteab@utah.gov>

---

## 2017 Annual Report Review Completion

---

**Suzanne Steab** <suzannesteab@utah.gov>  
To: Chris Hansen <chansen@bowieresources.com>  
Cc: "Christensen, Steve" <stevechristensen@utah.gov>

Wed, Apr 11, 2018 at 9:27 AM

Hello Chris,

The Division staff has completed the review of the 2017 Annual Report for the Gordon Creek #2, #7 & #8 Mine. Attached is a copy of the review with comments.

No hard copy will follow.

Thank you for your diligence in completing the Annual Report.

--

Suzanne Steab, Engineering Technician II  
Division of Oil, Gas & Mining  
1594 West North Temple, Suite 1210  
Salt Lake City, Utah 84114-5801  
(801) 538-5265

---

 **Gordon.pdf**  
33K

# ANNUAL REPORT

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

## GENERAL INFORMATION

Company Name	Canyon Fuel Company, LLC	Mine Name	Gordon Creek 2, 7 & 8
Permit Number	C/007/0016	Permit expiration Date	2019-08-28
Operator Name	Canyon Fuel Company, LLC	Phone Number	+1 (435) 448-2669
Mailing Address	HC 35 Box 380	Email	chansen@bowieresources.com
City	Helper		
State	Utah	Zip Code	84526

## DOGM File Location or Annual Report Location

Excess Spoil Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Refuse Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Attached.
Other:		

## OPERATOR COMMENTS

**REVIEWER COMMENTS**     Met Requirements     Did Not Meet Requirements

The submittal includes scanned copies of two quarterly pond inspections of the Gordon Creek 2, 7 & 8 Mines Jacob Pond The pond inspections are dated 5/16/2017 and 9/17/2017. The annual inspection was performed by Jacob Smith and Vicky Miller of Canyon Fuel Company's Sufco Mine in 10/19/2017.

## REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

Reviewer Comments

Three quarterly inspections of Jacob's Pond were completed during 2017: one report was completed by Chris Hansen on 5/16/17, and again by Vicky Miller on 9/17/17 and 10/19/17. The inspection report conducted on 10/19 was signed and stamped by Jacob D. Smith, a Professional Engineer for the State of Utah. These reports complete the annual impoundment certification requirement established under R645-301-514.312. No signs of instability in the embankment or spillway were identified during the inspections, and reported no discharge in all three cases. This is not a reported UPDES outfall location, and the water that reports to Jacob's Pond is most prominently supplied by a spring located in the north bank above the pond. JE

