

INSPECTION REPORT  
(Page 2)

Permit Number: ACT/007/018

Date of Inspection: 8-20-86

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

4.c. Sediment Ponds and Impoundments:

1) Construction is currently being performed on the operator's sediment pond. The construction is remedial action related to NOV N85-4-15-1 issued by Dave Lof for improper maintenance and construction of the sediment pond. The Division has requested that the operator complete construction by August 30, 1986. At the time of this inspection the sediment pond is nearly completed. All that remains to be done is the breaking up and placing of some large boulders against the toe of the embankment.

The operator felt confident that the pond construction would be finished before the 30th of August. Also he indicated that seeding and fencing would be completed by Oct. 1, 1986.

The NOV concerning the pond will be terminated, after the 30th as soon as DOGM personnel are able to verify that the work is satisfactory.

2) Both the sediment pond and sewage lagoon are inspected quarterly. The last inspection for each was dated 6-16-86.

4.e. Surface and Groundwater Monitoring:

1) According to the operator's schedule for water monitoring all information is current up through 6-11-86.

2) Mr. Spillman related to me that the operator would like to eliminate his obligation to monitor in mine, groundwater discharges of less than 3 gpm. I advised Mr. Spillman that I would look into it and get back to him with information regarding this requirement.

Copy of this Report:

Mailed to: Dave Spillman, Donna Griffin

Given to: Joe Hellrich, Sue Lianey

Inspectors Signature and Number: Hollis Shepherd #9 9-5-86

0365Q 1-2