

0007



Canyon Fuel Company, LLC
Soldier / Dugout Canyon Mines
P.O. Box 1029
Wellington, Utah 84542
435/637-6360 Fax: 435/637-0108

March 31, 1999

Utah Coal Regulatory Program
Attn: Mary Ann Wright
Utah Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

*** THIS annual report
is filed under
Soldier Canyon*

Re: Submittal of the 1998 Annual Reports
Soldier Canyon Mine, ACT/007/018 #6
Banning Loadout, ACT/007/034

Copy #6 -

Dear Ms. Wright:

Enclosed please find two copies of the 1998 annual reports for the Soldier Canyon Mine and Banning Loadout. The annual report for the Dugout Canyon Mine will be forwarded from Canyon Fuel Company's Skyline operation.

Should you have any questions concerning this submittal, please contact me directly at (435)636-2872.


Sincerely,
SOLDIER / DUGOUT CANYON MINES

David G. Spillman

David G. Spillman, P.E.
Technical Services Manager

enclosures

cc: Chris Hansen, Skyline
Central Files



Original
007/020 #6
cc Bill

1998 Annual Report Review

Permittee: Horizon Mining, LLC
 Mine Name: Horizon Mine
 Permit Number: ACT/007/020
 Date Report Received 03/31/99
 Assigned Reviewers: Bill Malencik, Wayne Western, Susan White
Sharon Falvey

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine folder #6.

Assignments: Inspectors: Review cover sheet, AVS legal/financial, Mine sequence map
Hydrologists: Review water monitoring data, Precipitation and climatological data, Non-coal waste
Biologists: Review vegetation/revegetation success monitoring, Raptor survey
Engineers: Review subsidence monitoring data, Annual impoundment certification, Annual overburden, spoils, refuse, floor, etc.

Section to review	Submitted Yes	No	Findings
Cover sheet	<u>X</u>	—	
AVS; Legal/Financial Update	<u>X</u>	—	
Mine Sequence Map	—	<u>X</u>	Mine sequence map (mine map) was submitted but not certified as required by R645-301-521.111 and R645-301-512
Water Monitoring Data	—	<u>X</u>	Quarterly water monitoring data submitted to the Division is not complete. The applicant has failed to submit data on volumes of water pumped from the mine and has failed to provide the groundwater monitoring samples according to Table 7-2. Commitments for sampling during the period until point 002 is approved at surface water sources were not consistently collected. A map showing the groundwater flow region and pump sump locations is needed.
Precipitation & Climatological Data	—	<u>X</u>	No precipitation or monitoring gauge is provided by the permittee at this site.

Non-Coal Waste report	—	<u>X</u>	No information on non coal waste was provided.	
Subsidence monitoring data	-	—	<u>X</u>	Permittee says to see letter under separate cover from Denise Dragoo. The Division does not have a copy of the letter in its files. The Permittee is having technical problems (does not know how to use the software) with showing the subsidence data.
Annual Impoundment Certification	-	<u>X</u>	—	The one sediment pond has been inspected no problems noted.
Annual Overburden, Spoil, Refuse, Floor, etc.	-	<u>X</u>	—	Inspection reports for temporary refuse piles were included. No problems were reported.
Vegetation data		—	<u>X</u>	
Revegetation Success monitoring		—	<u>X</u>	
Raptor survey		<u>X</u>	—	A map titled 1998 Raptor Survey Jump Creek Quad was submitted. No legend or other information concerning the survey was provided. The map has no meaning without a description of the map and survey methods.
Other information		—	—	

O:\007020.HZN\ANNUALRP\REVIEW.FRM