



355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

May 9, 1988

TO: Sue Linner, Permit Supervisor / Reclamation Biologist  
FROM: James S. Leatherwood, Reclamation Soils Specialist  
Re: Determination of Completeness and Technical  
Deficiencies, Aberdeen Mine Development, Andalex  
Resources, ACT/007/019, Folder No. 2, Carbon County,  
Utah

The above mentioned submittal, received March 25, 1988, has been reviewed and found to be complete but not adequate. The following items should be addressed.

UMC 817.22 Topsoil: Removal - JSL

Section 2.2, page 61 of the Permit Application Package (PAP) should be updated to reflect the depth of topsoil removal as specified in section 4.3, page 87 of the PAP (eg. 11 inches).

UMC 817.24 Topsoil: Redistribution - JSL

Section 5.3, page 104, and section 3, page 101 should be updated to include the specific depth of topsoil redistribution as stated in section 2.2, page 61 of the PAP.

as/JSL  
cc. D. Darby  
0534R/82