



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

9-18-88

File

su

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

REVISED COPY

INSPECTION REPORT

INSPECTION DATE & TIME: March 3, 1988
9:30 a.m. to 11:30 a.m.

Permittee and/or Operators Name: Andalex Resources
Business Address: P. O. Box 902 Price, Utah 84501
Mine Name: Centennial Project Permit Number: ACT/007/019
Type of Mining Activity: Underground Surface Other
County: Carbon State: Utah
Company Official (s): Mike Glasson
State Official(s): Daron Haddock
Partial: Complete: Date of Last Inspection: Feb. 11, 1988
Weather Conditions: Clear and sunny
Acreage: Permitted 2360 Disturbed 31 Regraded Seeded Bonded 31
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	(X)	()	()	(X)
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/019
INSPECTION March 3, 1988

DATE OF

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS:

A conditional permit was issued March 3, 1987. The conditions of the permit have not as yet been met even though Andalex has made three (3) submittals.

On Dec. 23, 1987, Andalex was issued NOV 87-9-17-1 for not answering the special permit stipulations, and given till March 1, 1988, to submit a comprehensive and well organized MRP.

ON Feb. 28, 1988, Andalex asked for and was granted a modification to extend the time for submitting the MRP to March 10, 1988. Mr. Glasson indicated that he would have the MRP submitted by that date. He also stated that plans for a new Aberdeen portal would be included in the plan as well as a plan for disposal of sediment and coal waste material.

2. SIGNS AND MARKERS:

Mine and permit identification signs are in place. Perimeter markers are well placed and visible (orange steel posts).

4b. DIVERSIONS:

A small amount of rock and debris has fallen into several of the ditches around the site due to spring thawing cycles. There is no significant hindrance to drainage at the present time; however, I asked Mr. Glasson to have the ditches and culverts cleaned as part of spring maintenance. This he agreed to do.

4c and 6. SEDIMENT PONDS AND WASTE DISPOSAL:

The upper two cells of pond B are still full of sediment from an event that happened last fall. The material has been tested and found to be non-toxic and non-hazardous. Plans are being formulated to use this material as fill during the construction of the new Aberdeen portal, which should be within two or three months. A plan is also being incorporated in the MRP to allow for the disposal of any future sediment or coal waste.

The second dike in pond B needs to have more rock placed on the lower side. Mr. Glasson will have this done when the pond is cleaned.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION March 3, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

4f. EFFLUENT LIMITATIONS:

There has been no discharge in the last month.

16d. ROAD MAINTENANCE:

All snow appeared to be placed where melt will drain to a sediment pond.

Copy of this Report:

Mailed to: Mike Glasson, Andalex

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: Daron R. Haddock #28 Date: March 5, 1988