

007/019 #2




0020

ANDALEX
RESOURCES, INC.
Tower Division

P.O. BOX 902
PRICE, UTAH 84501
PHONE (801) 637-5385
TELECOPIER (801) 637-8860

June 1, 1992



State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Attn.: Daron Haddock, Permit Supervisor

Re.: ACT 007/019 Minor Modification

Dear Mr. Haddock:

Pursuant to discussions with your office, I am enclosing two copies each of "Appendix R" divider so that you may insert the previously submitted surface owner comments therein. I have also enclosed two copies each of text page 78 which now references Appendix R.

I have also enclosed revised text for your review which effectively removes reference to riprap protection in diversion UD-2 east of the main office. It is our experience that this protection is unnecessary. Andalex is committed to maintaining UD-1 in efficient working order; it should be noted a lack of runoff from this watershed over the past 12 years has been observed. No reference to this erosion protection is made on our surface facilities or surface drainage plates.

Please call with questions.

Sincerely,

Michael W. Glasson
Senior Geologist

MWG/as

cc: File



JUN 08 1992

DIVISION OF
OIL GAS & MINING