

0029



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

January 24, 1992

Mr. Sam Quigley
Andalex Resources, Inc.
P. O. Box 902
Price, Utah 84501

Dear Mr. ^{Sam} Quigley:

Re: Division Order #92A, Andalex Resources, Inc., Centennial Project, ACT/007/019,
Folder #3, Carbon County, Utah

During a review of your MRP and recent spillway amendment a number of permit defects were encountered relative to Pond C. Enclosed is a Division Order requiring correction of those permit defects. Please note that the deadline for completing the Division Order is March 9, 1992.

The review was conducted by Rick Summers, Senior Reclamation Hydrologist, and we encourage you to contact him for further detail on the defects encountered.

Thank you for your cooperation during the permitting process.

Best regards,

A handwritten signature in cursive script, appearing to read 'Dianne'.

Dianne R. Nielson
Director

Attachments

cc: R. Hagen, OSM
L. Braxton, DOGM
B-Team
ANDAPOND.DO

**STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING**

PERMITTEE

**Mr. Sam Quigley
General Manager
Andalex Resources, Inc.
P. O. Box 902
Price, Utah 84501**

**Centennial Mines Project
Carbon County, Utah**

**Permit Number ACT/007/019
Division Order # 92-A**

**DIVISION ORDER AND FINDINGS
of
PERMIT DEFICIENCY**

PURSUANT to R645-303-212, the DIVISION hereby ORDERS the PERMITTEE, Andalex Resources Inc., to make the permit changes enumerated in the FINDINGS OF PERMIT DEFICIENCY in order to be in compliance with the State Coal Program. These Findings of Permit Deficiency are to be remedied in accordance with the requirements of R645-303-220.


FINDINGS OF PERMIT DEFICIENCY

Based on a review of Andalex's MRP and amendment ACT/007/019-91A there appear to be discrepancies relative to the assumptions and calculations for Pond C designs. Values presented are not consistent and cannot be accepted by the Division. Andalex Resources, Inc. will be required to correct the permit defects relative to Pond C and demonstrate compliance with R645-301-733 and R645-301-742.220.

ORDER

It is hereby ORDERED that Andalex Resources, Inc. make the requisite permit changes in accordance with R645-303-220 and submit a complete application for permit change, addressing the FINDINGS OF PERMIT DEFICIENCY by no later than March 9, 1992.

So ORDERED, this 23rd day of January, 1992, by the Division of Oil, Gas and Mining.


Dianne R. Nielson, Director
Division of Oil, Gas and Mining