



SCOTT M. MATHESON
Governor

OIL, GAS, AND MINING BOARD

CHARLES R. HENDERSON
Chairman

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS, AND MINING

1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
CONSTANCE K. LUNDBERG
EDWARD T. BECK
E. STEELE McINTYRE

CLEON B. FEIGHT
Director

October 15, 1980

Mr. Joseph A. Harvey
Blazon Mining Company
P.O. Box 327
Ferron, Utah 84523

RE: Modifications
Blazon #1 Mine
ACT/007/021

Dear Mr. Harvey:

The Division staff has reviewed your October 2, 1980 submittal regarding the changes to be made to the surface design of the Blazon #1 Mine. The Division hereby approves the modification of the portal access road, modification of the location of the water tank and modification of the shape of the sediment pond with the following stipulations:


1. Modification of the portal access road must incorporate as much topsoil removal and stockpiling as is possible to provide Blazon Mine with sufficient material for final reclamation.
2. Modification of the water tank location is acceptable, however, the access road to the water tank substation pad must conform with UMC 817.172(a) for design and construction of Class III roads.

Mr. Joseph A. Harvey
October 15, 1980
Page Two

3. The shape of the sediment pond can be modified as long as the storage capacity will remains the same. In addition, the outslope of the sediment pond bordering on the temporary creek diversion must be riprapped to prevent erosion during periods of high flow. Special attention should be given to sediment control during construction of the sediment pond due to the proximity to the creek.

If you have any questions, please call me or Tom Suchoski of my staff.

Sincerely,



JAMES W. SMITH, JR.
COORDINATOR OF MINED LAND DEVELOPMENT

JWS/te

cc: Don Crane, O.S.M.