



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: XX Complete: Exploration

Inspection Date/Time: October 29, 1993/08:00am-12:00pm

Date of Last Inspection: September 9, 1993

Mine Name: Blazon #1 County: Carbon Permit Number: ACT/007/021
 Permittee and/or Operator's Name: NAE (Insolvent), no known mailing address
 Business: Mail cc attn: Steve Tanner, Route #1, Box 146G3, Helper, UT 84526 637-5986
 Type of Mining Activity: Underground XX Surface Prep. Plant Other
 Officials(s): State: Stephen J. Demczak Company:
 Federal Officials: Weather Conditions: Snowing 20's
 Existing Acreage: Permitted- 0 Disturbed- 4.5 Regraded- 2.5 Seeded- 2.5 Bonded- 0
 Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
 Status: Exploration/ Active/ Inactive/ Temp Cessation/XX Bond Forfeiture
 Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[]	[XX]	[]
2. SIGNS AND MARKERS	[]	[]	[]	[]
3. TOPSOIL	[]	[]	[]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[]	[XX]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[]	[]	[]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[]	[]	[]	[]
d. WATER MONITORING	[]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[]	[]	[]	[]
5. EXPLOSIVES	[]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[]	[]	[]	[]
8. NONCOAL WASTE	[]	[]	[]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[XX]	[]	[XX]	[]
11. CONTEMPORANEOUS RECLAMATION	[]	[]	[]	[]
12. BACKFILLING AND GRADING	[]	[]	[]	[]
13. REVEGETATION	[]	[]	[]	[]
14. SUBSIDENCE CONTROL	[]	[]	[]	[]
15. CESSATION OF OPERATIONS	[]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[]	[]	[]	[]
b. DRAINAGE CONTROLS	[]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June) <u> </u> date	[]	[]	[]	[]
20. AIR QUALITY PERMIT	[]	[]	[]	[]
21. BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021 DATE OF INSPECTION: October 29, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

- a) The North American Equities as an entity no longer exists. There is no agent for service for notice or regulatory action.
- b) The forfeiture of the reclamation bond is for the amount of \$38,000. The preliminary estimate of the monies required to reclaim the site for use of wildlife and grazing may exceed \$100,000.
- c) There is no apparent activity at the site since the last inspection.

4a. Diversions -

There was no water flowing at the time of the inspection. The diversions are silted at several locations and small size rocks are within the ditches throughout the diversions. Silt fences are in need repair as in previous inspections.

10. Slides and Other Damages -

There is no evidence of sliding or additional movement occurring at the site.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: _____
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: November 1, 1993

Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak