

June 30, 2003

James Fulton, Chief, DFD
Office of Surface Mining
1999 Broadway, Suite 3320
Denver, Colorado 80202-5733

Re: Inspection Frequency Change for Abandoned Mine Sites, Sunnyside Mine, C/007/007, Blazon Mine, C/007/021, Black Jack #1 Mine, C/019/004, Summit #1 Mine, C/041/001, Boyer Mine, C/041/008, Outgoing File

Dear Mr. Fulton:

Enclosed are the findings to change the inspection frequency for the five above-noted abandoned mine sites from four inspections per year to one per year.

If you have any questions, please feel free to call Pamela Grubaugh-Littig at (801) 538-5268 or me at (801) 538-5306.

Sincerely,

Mary Ann Wright
Associate Director, Mining

an
Enclosure
cc: Price Field Office
O:\007007.SUN\FINAL\inspfreqchangeOSM.doc

FINDINGS
INSPECTION FREQUENCY CHANGE
Sunnyside Mine

Sunnyside Mine
Sunnyside Coal Company
C/007/007

The Sunnyside Mine is considered an abandoned site because it meets the criteria of the definition of an abandoned site, “(a) All coal mining and reclamation operations at the site have ceased” and (d)(ii) “The Division forfeited the performance bond and reclaimed the site.” The Division of Oil, Gas and Mining proposes that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year as required by R645-301-100. This frequency is in lieu of the inspection frequency of four times per year established in R645-400-130.

There are no impoundments, earthen structures, or other conditions that pose, or may reasonably be expected to change into, imminent dangers to the health or safety of the public or significant environmental harms to lands, air or water resources. Vegetation establishment is preventing erosion and the drainages have been re-established and are functioning. This site is located near the small towns of Sunnyside and East Carbon, Utah.

The reclamation bond for this mine was forfeited on November 22, 1996 and the mine was reclaimed as of July 1, 1999. The public notice was published on March 11, 2003 in the Sun Advocate and no comments were received.

The site is stable and Grassy Trail Creek was reestablished on the edge of the permit area to an aesthetic and natural condition. The site was inspected on January 29, 2003 June 18, 2003. There are no outstanding environmental, public health or safety conditions that are present.

Therefore, the inspection frequency will change, effective June 30, 2003.

The Sunnyside Mine is located on:

Fee Land

Township 14 South, Range 14 East, SLB&M, Utah

Sec. 6: N1/2, S1/2 SW1/4, S1/2 SE1/4. NW1/4 SE1/4,
Sec. 7: NW1/4, SW 1/4 NE1/4, E1/2 SW1/4, S1/2 SE1/4, NW1/4 SE1/4,
Sec. 17: NE1/4, SE1/4 NW1/4, SW1/4 SE1/4, S1/2 SE1/4,
Sec. 18: E1/2, S1/2 SW1/4, NE1/4 SW1/4, NW1/4 SW1/4, SW1/4 NW1/4 less the following described area:

Beginning at the NW corner of SW1/4 NW1/4 of Section 18, Township 14 South, Range

14 East:

thence S 45° 05' E, 1,577.42 ft;

thence S 39° 25' W, 1,759.22 ft; and

thence N 2,472.87 ft to point of beginning.

Secs.19 and 20: All,
Sec.21: W1/2,
Secs.28 and 29: All,
Sec.30: NE1/4, NE1/4 NW1/4, NW1/4 SE1/4,
Sec.31: S1/2 NE1/4, NE1/4 NE1/4,
Secs.32 and 33: All, and
Sec.34: W1/2.

Township 15 South, Range 14, East, SLB&M, Utah

Sec.3: W1/2,
Sec.4: All,
Sec.5: NE1/4, N1/2 SE1/4, SE1/4SE1/4, W1/2, SW1/4 SE1/4,
Sec.6: S1/2 SE1/4, SE1/4 SW1/4, portions of N1/2 SE1/4 and NE1/4 SW1/4,
South of the D&RGW Railroad right-of- way,
Sec.7: N1/2 NE1/4, N3/4 NW1/4,
Sec.8: NE1/4NE1/4, N1/2 NW1/4NW1/4 NE1/4,
Sec.9: All,
Sec.10: W1/2, SE1/4,
Sec.15: W1/2, N1/2 NE1/4,
Sec.16: E1/2, NW1/4, E1/2 SW1/4, and
Sec.17: E1/2 NE1/4,

Federal Leases

Federal Coal Leases numbers Salt Lake 062966-063383-Utah 010140, Utah and SL-068754.
Areas within both the leases and the permit area are described as follows:

Township 14 South, Range 13 East, SLB&M, Utah

Sec.1: SE1/4, SE1/4 SE1/4 SW1/4,
Sec.12: NW1/4, NE1/4, SE1/4 NE1/4 SW1/4 less the following described area:

Beginning at a point which bears S 1,320 ft from the NW corner of Section 12:

thence S 1,320 ft;
thence S 89° 55'30" E, 1,327.01 ft;
thence S 1,320 ft;
thence S 89° 53'15" E, 1,327.22 ft;
thence S 1,320 ft;
thence S 89° 51' 15" E, 1,327.43 ft; and
thence N 45° 05' 07" W, 5,623.40 ft to the place of beginning.

Sec.13: Portions of: NE1/4 NE1/4, E1/2 SE1/4, SW1/4 SE1/4, SE1/4 SW1/4,
NE1/4 SW1/4, NW1/4 SW1/4, SW1/4 NW1/4,
Sec.24: S1/2 SE1/4, Portions of: N1/2 NE1/4, SE1/4 NE1/4, N1/2 SE1/4 and
NE1/4 SW1/4,
Sec.14: Portions of: NE1/4,
Sec.11: Portions of: SW1/4 SE1/4, and
Sec.25: NE1/4 NE1/4.

Township 14 South, Range 14 East, SLB&M, Utah

Sec.6: N1/2 SW1/4,
Sec.7: W1/2 SW1/4,
Sec.8: SW1/4SW1/4 SE1/4,
Sec.17: W1/2 NW1/4, NE1/4 NW1/4, N1/2 SE1/4,
Sec.18: E1/2 NW1/4, NW1/4NW1/4,
Sec.30: NW1/4NW1/4, SE1/4 NW1/4, NE1/4 SW1/4, S1/2 SE1/4, NE1/4 SE1/4, and
Sec.31: NW1/4NE1/4.

Carbon County Lease

Township 14 South, Range 14 East, SLB&M, Utah

Sec.21: SE1/4,
Sec.27: SW1/4, SW1/4 NW1/4, and
Sec.34: E1/2.

Township 15 South, Range 14 East

Sec.3: E1/2 and
Sec.10: NE1/4.

AFFIDAVIT OF PUBLICATION

**PUBLIC NOTICE
SUNNYSIDE MINE
SUNNYSIDE MINE
SUNNYSIDE COAL COMPANY
C/007/007**

*2/20/07
C/007/007
Copy Frank*

STATE OF UTAH)

SS.

County of Carbon,)

I, Ken Larson, on oath, say that I am the Publisher of the Sun Advocate, a twice-weekly newspaper of general circulation, published at Price, State a true copy of which is hereto attached, was published in the full issue of such newspaper for 1 (One) consecutive issues, and that the first publication was on the 11th day of March, 2003, and that the last publication of such notice was in the issue of such newspaper dated the 11th day of March, 2003.

Ken G. Larson


Ken G Larson - Publisher

Subscribed and sworn to before me this 11th day of March, 2003.

Linda Mayn

Notary Public My commission expires January 10, 2007 Residing at Price, Utah

Publication fee, \$ 274.72



The reclamation bond for this mine was forfeited on November 22, 1996 and the area was reclaimed as of July 1, 1999. Since the Sunnyside Mine is considered an abandoned site, the Division of Oil, Gas and Mining proposes in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year. This site was last inspected on January 29, 2003, and no threats to public safety or environment were noted.

The Sunnyside Mine is located on:
Fee Land

- Township 14 South, Range 14 East, SLB&M, Utah
- Sec. 6: N1/2, S1/2 SW1/4, S1/2 SE1/4, NW1/4 SE1/4,
- Sec. 7: NW1/4, SW 1/4 NE1/4, E1/2 SW1/4, S1/2 SE1/4, NW1/4 SE1/4,
- Sec. 17: NE1/4, SE1/4 NW1/4, SW1/4 SE1/4, S1/2 SE1/4,
- Sec. 18: E1/2, S1/2 SW1/4, NE1/4 SW1/4, NW1/4 SW1/4, SW1/4 NW1/4 less the following described area:

Beginning at the NW corner of SW1/4 NW1/4 of Section 18, Township 14 South, Range 14 East:

- thence S 45° 05' E, 1,577.42 ft;
- thence S 39° 25' W, 1,759.22 ft; and
- thence N 2,472.87 ft to point of beginning.

- Secs.19 and 20: All,
- Sec.21: W1/2,
- Secs.28 and 29: All,
- Sec.30: NE1/4, NE1/4 NW1/4, NW1/4 SE1/4,
- Sec.31: S1/2 NE1/4, NE1/4 NE1/4,
- Secs.32 and 33: All, and
- Sec.34: W1/2.

- Township 15 South, Range 14, East, SLB&M, Utah
- Sec.3: W1/2,
- Sec.4: All,
- Sec.5: NE1/4, N1/2 SE1/4, SE1/4SE1/4, W1/2, SW1/4 SE1/4,
- Sec.6: S1/2 SE1/4, SE1/4 SW1/4, portions of N1/2 SE1/4 and NE1/4 SW1/4, South of the D&RGW Railroad right-of-way,
- Sec.7: N1/2 NE1/4, N3/4 NW1/4,
- Sec.8: NE1/4NE1/4, N1/2 NW1/4NW1/4 NE1/4,
- Sec.9: All,
- Sec.10: W1/2, SE1/4,
- Sec.15: W1/2, N1/2 NE1/4,
- Sec.16: E1/2, NW1/4, E1/2 SW1/4, and
- Sec.17: E1/2 NE1/4,

Federal Leases
Federal Coal Leases numbers Salt Lake 062966-063383-Utah 010140, Utah and SL-068754. Areas within both the leases and the permit area are described as follows:

- Township 14 South, Range 13 East, SLB&M, Utah
- Sec.1: SE1/4, SE1/4 SE1/4 SW1/4,
- Sec.12: NW1/4, NE1/4, SE1/4 NE1/4 SW1/4 less the following described area:

Published in the Sun Advocate March 11, 2003.

FINDINGS
INSPECTION FREQUENCY CHANGE
Blazon Mine

Blazon Mine
North American Equities Inc.
C/007/021

The Blazon Mine is considered an abandoned site because it meets the criteria of the definition of an abandoned site, “(a) All coal mining and reclamation operations at the site have ceased” and (d)(ii) “The Division forfeited the performance bond and reclaimed the site.” The Division of Oil, Gas and Mining proposes that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year as required by R645-301-100. This frequency is in lieu of the inspection frequency of four times per year established in R645-400-130.

There are no impoundments, earthen structures, or other conditions that pose, or may reasonably be expected to change into, imminent dangers to the health or safety of the public or significant environmental harms to lands, air or water resources. Vegetation establishment is preventing erosion and the drainages is re-established and functioning. This site is not located near an urbanized area, although the small town of Clear Creek is about a mile away.

The reclamation bond for this mine was forfeited on May 24, 1991 and the mine was reclaimed as of October 4, 2000. The public notice was published on March 11, 2003 in the Sun Advocate and no comments were received.

The site is stable and the stream has been reestablished. The site was inspected on January 28, 2003 and April 9, 2003. There are no outstanding environmental, public health or safety conditions that are present.

Therefore, the inspection frequency will change, effective June 30, 2003.

Blazon Mine is located on:

Fee Land

T 14 S R 7E, SLB&M

Section 4: S1/2NW1/4, N1/2 SW1/4 (242.5 AC)

AFFIDAVIT OF PUBLICATION

*incoming
d/007/021
Copy from ✓*

STATE OF UTAH)

ss.

County of Carbon,)

I, Ken Larson, on oath, say that I am the Publisher of the Sun Advocate, a twice-weekly newspaper of general circulation, published at Price, State a true copy of which is hereto attached, was published in the full issue of such newspaper for 1 (One) consecutive issues, and that the first publication was on the 11th day of March, 2003, and that the last publication of such notice was in the issue of such newspaper dated the 11th day of March, 2003.

Ken G. Larson

Ken G Larson - Publisher

Subscribed and sworn to before me this 11th day of March, 2003.

Linda Thayne

Notary Public My commission expires January 10, 2007 Residing at Price, Utah

Publication fee, \$ 72.72

**PUBLIC NOTICE
BLAZON MINE
BLAZON MINE
NORTH AMERICAN EQUITIES INC.
C/007/021**

The reclamation bond for this mine was forfeited on May 24, 1991 and the mine was reclaimed as of October 4, 2000. Since the Blazon Mine is considered an abandoned site, the Division of Oil, Gas and Mining proposes in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year. The site was last inspected in January 28, 2003, and no threats to public safety or the environment were noted.

Blazon Mine is located on:

Fee Land


T 14 S R 7E, SLB&M

Section 4: S1/2NW1/4, N1/2 SW1/4 (242.5 AC)

If you have any comments about the proposed reduction in frequency of inspections at this mine, please send written comments within 30 days to:

Mary Ann Wright, Associate Director, Mining
Division of Oil, Gas & Mining
1594 West North Temple, Suite 1210
Salt Lake City, Utah 84114

Published in the Sun Advocate March 11, 2003.



FINDINGS
INSPECTION FREQUENCY CHANGE
Black Jack #1 Mine

Black Jack #1 Mine
New Tech Mining Corp.
C/019/004

The Black Jack #1 is considered an abandoned site because it meets the criteria of the definition of an abandoned site, “(a) All coal mining and reclamation operations at the site have ceased” and (d)(ii) “The Division forfeited the performance bond and reclaimed the site.” The Division of Oil, Gas and Mining proposes that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year as required by R645-301-100. This frequency is in lieu of the inspection frequency of four times per year established in R645-400-130.

There are no impoundments, earthen structures, or other conditions that pose, or may reasonably be expected to change into, imminent dangers to the health or safety of the public or significant environmental harms to lands, air or water resources. Limited vegetation establishment is preventing erosion. This site is not located near an urbanized area, although the small town of Thompson is about seven miles away.

The reclamation bond for this mine was forfeited in 1990 and the mine was reclaimed in November 1992. The public notice was published on March 14, 2003 in the Times-Independent in Moab, Utah. No comments were received.

The site was inspected on January 30, 2003 and June 19, 2003. There are no outstanding environmental, public health or safety conditions that are present.

Therefore, the inspection frequency will change, effective June 30, 2003.

Black Jack #1 Mine is Located on:

Fee Land

T20S, R20E, SLB&M

Section 29: NE1/4

PUBLIC NOTICE

**Black Jack #1 Mine
New Tech Mining
Corp.
C/019/004**

The Reclamation Bond for this coal exploration project was forfeited in 1990 and the project was reclaimed November 1992. Since the Black Jack #1 Mine is considered an abandoned site, the Division of Oil, Gas and Mining proposes, in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year. The site was last inspected on January 30, 2003, and no threats to public safety or the environment were noted.

Black Jack, #1 Mine is Located on:
Fee Land, T20S, R20E, SLB&M, Section 29: NE-1/4

If you have any comments about the proposed change in frequency of inspections of this reclaimed mine, please send written comments within 30 days to:

Mary Arm Wright,
Associate Director,
Mining
Division of Oil, Gas &
Mining
1594 West North
Temple, Suite 12 10
Salt Lake City, Utah
84114

Published in The Times-Independent, Moab, Utah, Mar. 13, 2003.

Proof of Publication

STATE OF UTAH,)
County of Grand,) ss.

Samuel J. Taylor or Adrien F. Taylor, being first duly sworn according to law, deposes and says: That he/she is the co-publisher of The Times-Independent, a weekly newspaper of general circulation, published every Thursday at Moab, Grand County, State of Utah; that the notice

Black Jack Mine Notice


hereto attached, and which is made a part of this Affidavit of Publication, was published in said newspaper for a period of 1 consecutive issues, the first publication date having been made March 13, 2003

;and the last on


;and the said notice was published in each and every copy of said newspaper during the period and time of publication, and that it was published in the newspaper proper and not in a supplement thereof.


Co-Publisher

Subscribed and sworn before me this


Notary Public
Residing at Moab, Utah

My Commission Expires



RECEIVED

JUN 09 2003

FINDINGS
INSPECTION FREQUENCY CHANGE
Summit Mine

Summit #1 Mine
Summit Coal Company
C/043/001

The Summit #1 Mine is considered an abandoned site because it meets the criteria of the definition of an abandoned site, “(a) All coal mining and reclamation operations at the site have ceased” and (d)(ii) “The Division forfeited the performance bond and reclaimed the site.” The Division of Oil, Gas and Mining proposes that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year as required by R645-301-100. This frequency is in lieu of the inspection frequency of four times per year established in R645-400-130.

There are no impoundments, earthen structures, or other conditions that pose, or may reasonably be expected to change into, imminent dangers to the health or safety of the public or significant environmental harms to lands, air or water resources. Vegetation establishment is preventing erosion. This site is not located near an urbanized area, although the small town of Coalville is about five miles away.

The reclamation bond for this mine was forfeited on June 13, 1989 and the mine was reclaimed as of April 17, 1997. The public notice was published on March 14, 2003 in the Summit County Bee (newspaper in Coalville) and March 12, 2003 in the Park Record (newspaper in Park City). No comments were received.

The site is stable and the stream has been reestablished. The site was inspected on January 28, 2003 and May 6, 2003. There are no outstanding environmental, public health or safety conditions that are present.

Therefore, the inspection frequency will change, effective June 30, 2003.

The Summit Mine is located on:

Fee Land

T3N R6E, SLB&M, Utah

Sec 36: NE1/4 NE1/4, SW1/4 NE1/4 and SE1/4 NE1/4.

PROOF OF PUBLICATION



*Incoming
C/043/008
copy PAM*

STATE OF UTAH, }
County of Summit, } ss.

I, Nancy Davis

being first duly sworn, depose and say that I am the _____

Bookkeeper of The Summit County Bee, a week-

ly newspaper of general circulation, published once each week at

Coalville, Utah, that the notice attached hereto and which is a

Public Notice

was published in said newspaper for One con-

secutive issues, the first publication having been made on the

14 day of March, 2003, and the last

on the 14 day of March, 2003, that said

notice was published in the regular and entire issue of every number

of the paper during the period and times of publication, and the same

was published in the newspaper proper and not in any supplement.

Nancy Davis

Subscribed and sworn to before me this 14 day of March, 2003

NOTARY PUBLIC
STATE OF UTAH
My Commission Expires

Laurie [Signature]

PUBLIC NOTICE
Summit Mine
Summit #1 Mine
Summit Coal Company
C/043/001

The reclamation bond for this Exploration project was forfeited on June 13, 1989 and the project site was reclaimed as of April 17, 1997. Since the Summit #1 Mine is considered an abandoned site, the Division of Oil, Gas and Mining proposes in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year. This site was last inspected on January 22, 2003 and no threats to public safety or the environment were noted.

The Summit Mine is located on:

Fee Land
T3N R6E, SLB&M.
Utah

Sec 36: NE1/4 NE1/4, SW1/4 NE1/4 and SE1/4 NE1/4.

If you have any comments about the proposed reduction in the frequency of inspections for this reclaimed mine, please send written comments within 30 days to:


Mary Ann Wright,
Associate Director, Mining
Division of Oil, Gas & Mining
1594 West North Temple, Suite 1210
Salt Lake City, Utah
84114.

Published in The Summit County Bee March

... ..
14 day of March, 2003, and the last
on the 14 day of March, 2003, that said
notice was published in the regular and entire issue of every number
of the paper during the period and times of publication, and the same
was published in the newspaper proper and not in any supplement.

Doray Davis

Subscribed and sworn to before me this 14 day of
March, 2003



Laurie B. Wynn
Notary Public

My commission expires 8/25/04

located on:
Fee Land
T3N R6E, SLB&M,
Utah
Sec 36: NE1/4 NE1/4,
SW1/4 NE1/4 and SE1/4
NE1/4.

If you have any comments about the proposed reduction in the frequency of inspections for this reclaimed mine, please send written comments within 30 days to:

Mary Ann Wright,
Associate Director, Mining
•Division of Oil, Gas &
Mining
1594 West North
Temple, Suite 1210
Salt Lake City, Utah
84114.

Published in The
Summit County Bee March
14, 2003.

P1560 3200000297A

PROOF OF PUBLICATION

STATE OF UTAH
County of Summit

2 Notices for a
Total \$ 125.10
2/043/001

I, Stephanie Borders, [Signature]
duly sworn, depose and say that I am Accountant,
Record, a bi-weekly newspaper of general circulation.
The notice attached hereto and which is a/an:

ADVERTISING COPIES		
FILE	PIC	OTHER
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

"Public Notice"

Was published in said newspaper for 1
publication having been made of the 12 days
2003, and the last on the 12 day of November, 2003, and
said notice was published in the regular and entire issue of every number of
the paper during the period of times of publication and the same was
published in the newspaper and not in any supplement. Total cost for this
legal is \$ 60.30. Reference billing No. 03525001.

Subscribed and sworn to me this 19 day of March, 2003.

PUBLIC NOTICE
Summit Mine

Summit #1 Mine
Summit Coal Company
C/043/001

[Signature]
Patricia A. Christensen


Patricia A. Christensen
Notary Public
My commission expires: November 9, 2004

The reclamation bond for this Exploration project was forfeited on June 13, 1989 and the project site was reclaimed as of April 17, 1997. Since the Summit #1 Mine is considered

an abandoned site, the Division of Oil, Gas and Mining proposes in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set as less than one complete inspection per calendar year. This site was last inspected on January 22, 2003 and no threats to public safety or the environment were noted.

The Summit Mines is located on:

Fee Land
T3N16E, SLB&M, Utah



RECEIVED
MAR 26 2003

0841 REE 6131 X6SM GCN2 NCINE03G

**Sec 36: NE1/4 NE1/4,
SW1/4 NE1/4 and SE1/4
NE1/4.**

If you have any comments about the proposed reduction in the frequency of inspections for this reclaimed mine, please send written comments within 30 days to:

Mary Ann Wright, Associate Director, Mining
Division of Oil, Gas & Mining
1594 West North Temple,
Suite 1210
Salt Lake City, Utah
84114

**PUBLISHED IN THE
PARK RECORD ON
WEDNESDAY, MARCH
12, 2003.**

FINDINGS
INSPECTION FREQUENCY CHANGE
Boyer Mine

Boyer Mine
Summit Coal Company
C/043/008

The Boyer Mine is considered an abandoned site because it meets the criteria of the definition of an abandoned site, “(a) All coal mining and reclamation operations at the site have ceased” and (d)(ii) “The Division forfeited the performance bond and reclaimed the site.” The Division of Oil, Gas and Mining proposes that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year as required by R645-301-100. This frequency is in lieu of the inspection frequency of four times per year established in R645-400-130.

There are no impoundments, earthen structures, or other conditions that pose, or may reasonably be expected to change into, imminent dangers to the health or safety of the public or significant environmental harms to lands, air or water resources. Vegetation establishment is preventing erosion. This site is not located near an urbanized area, although the small town of Coalville is about five miles away.

The reclamation bond for this mine was forfeited on October 20, 1995 and the mine was reclaimed as of November 20, 1997. The public notice was published on March 14, 2003 in the Summit County Bee (newspaper in Coalville) and March 12, 2003 in the Park Record (newspaper in Park City). No comments were received.

The site is stable and the stream has been reestablished. The site was inspected on January 22, 2003 and May 6, 2003. There are no outstanding environmental, public health or safety conditions that are present.

Therefore, the inspection frequency will change, effective June 30, 2003.

Boyer Mine is located on:

Fee Land

T3N R6E SLB&M, Utah

Sec 25: S1/2 S1/2,

Sec 36: North of the County Right of Way and a strip of land between the County highway and south of Chalk Creek running 800 feet west from the east side.

PROOF OF PUBLICATION



STATE OF UTAH, |
County of Summit, | ss.

I, Nancy Davis

being first duly sworn, depose and say that I am the _____

Bookkeeper of The Summit County Bee, a week-

ly newspaper of general circulation, published once each week at

Coalville, Utah, that the notice attached hereto and which is a

Public Notice

was published in said newspaper for One con-

secutive issues, the first publication having been made on the

14 day of March, 2003, and the last

on the 14 day of March, 2003, that said

notice was published in the regular and entire issue of every number


of the paper during the period and times of publication, and the same

was published in the newspaper proper and not in any supplement.

Nancy Davis

Subscribed and sworn to before me this 14 day of

March, 2003



Laurie B. Wynn
Notary Public

Lucy
C/043/008
Copy From

PUBLIC NOTICE
Boyer Mine
Boyer Mine
Summit Coal Company
C/043/008

The reclamation bond for this mine was forfeited on October 20, 1995 and the mine was reclaimed as of November 20, 1997. Since the Boyer Mine is considered an abandoned site, the Division of Oil, Gas and Mining proposes in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year. This site was last inspected on January 22, 2003, and no threats to public or the environment were noted.

Boyer Mine is located on:

Fee Land
T3N R6E SLB&M,
Utah

Sec. 25: S1/2S1/2

Sec 36: North of the County Right of Way and a strip of land between the County highway and south of Chalk Creek running 800 feet west from the east side.

If you have any comments about the proposed reduction in the frequency of inspections for this mine, please send written comments within 30 days of:

Mary Ann Wright,
Associate Director, Mining
Division of Oil, Gas &
Mining
1594 West North
Temple, Suite 1210
Salt Lake City, Utah
84114-5801

Published in The
Summit County Bee March


ly newspaper of general circulation. published once each week at Coalville, Utah, that the notice attached hereto and which is a

Public Notice

was published in said newspaper for One consecutive issues, the first publication having been made on the 14 day of March, 2003, and the last on the 14 day of March, 2003, that said notice was published in the regular and entire issue of every number of the paper during the period and times of publication, and the same was published in the newspaper proper and not in any supplement.

Nancy Davis

Subscribed and sworn to before me this 14 day of March, 2003



Laurie B. Wynn
Notary Public

My commission expires 8/25/04

considered, an abandoned site, the Division of Oil, Gas and Mining proposes in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year. This site was last inspected on January 22, 2003, and no threats to public or the environment were noted.

Boyer Mine is located on:

Fee Land
T3N R6E SLB&M,
Utah

Sec. 25: S1/2S1/2

Sec 36: North of the County Right of Way and a strip of land between the County highway and south of Chalk Creek running 800 feet west from the east side.

If you have any comments about the proposed reduction in the frequency of inspections for this mine, please send written comments within 30 days of:

Mary Ann Wright,
Associate Director, Mining
Division of Oil, Gas &
Mining
1594 West North
Temple, Suite 1210
Salt Lake City, Utah
84114-5801

Published in The
Summit County Bee March
14, 2003.

PL 560 32000000297B

PROOF OF PUBLICATION

*Copy from
C/043/008
Mining*

STATE OF UTAH
County of Summit

I, Stephanie Borders, *Stephanie Borders*, being first duly sworn, depose and say that I am Accounting Manager of The Park Record, a bi-weekly newspaper of general circulation, in Park City, Utah. The notice attached hereto and which is a/an:

"Public Notice Boyer Mine"

Was published in said newspaper for 1 consecutive issue(s), the first publication having been made of the 12 day of March, 2003, and the last on the 12 day of March, 2003, that said notice was published in the regular and entire issue of every number of the paper during the period of times of publication and the same was published in the newspaper and not in any supplement. Total cost for this legal is \$ 6480. Reference billing No. 03525002.

Subscribed and sworn to me this 19 day of March, 2003.


PUBLIC NOTICE
Boyer Mine

Boyer Mine
Summit Coal Company
C/043/008

Patricia A. Christensen

Patricia A. Christensen
Notary Public
My commission expires: November 9, 2004

The reclamation bond for this mine was forfeited on October 20, 1995 and the mine was reclaimed as of November 20, 1997. Since the Boyer Mine is considered an abandoned site, the Division of Oil, Gas and Mining proposes in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at least than one complete inspection per calendar year. This site was last inspected on January 22, 2003, and no threats to public or the environment were noted.



Boyer Mine is located on:

Fee Land
T3N R6E SLB&M, Utah

Sec 25: S1/2 S1/2,
North of the

2841/REE/6131/X6BY/GCN2/NCINE03G

and a strip of land between the County highway and south of Chalk Creek running 800 feet west from the east side.

If you have any comments about the proposed reduction in the frequency of inspections for this mine, please send written comments within 30 days to:

Mary Ann Wright, Associate Director, Mining
Division of Oil, Gas & Mining
1594 West North Temple,
Suite 1210
Salt Lake City, Utah
84114

**PUBLISHED IN THE
PARK RECORD ON
WEDNESDAY, MARCH
12, 2003.**

RECEIVED

MAR 28 2003

OFFICE OF THE DIRECTOR