



STATE OF UTAH
NATURAL RESOURCES & ENERGY
Oil, Gas & Mining

0030

ACT/007/022

Scott M. Matheson, Governor
Temple A. Reynolds, Executive Director
Cleon B. Feight, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

January 6, 1981

Mr. Ken W. Wangerud
Coordinator
Permits and Compliance
Arco Coal Company
555 Seventeenth Street
Box 5300
Denver, Colorado 80217

RE: Assessment Conference for
State Violation No. N81-4-2-1

Dear Mr. Wangerud:

Pursuant to your request of October 29, 1981, I have established
Friday, January 15, 1982, at 10:30 a.m., for the assessment conference
on State Violation No. N81-4-2-1.

The conference will be held in this office.

Please let me know if this arrangement creates any problems for you.

Sincerely,

RONALD W. DANIELS
ACTING ASSESSMENT OFFICER

RWD/te

cc: Carolyn Driscoll, Legal Specialist
Joe Helfrich, Field Supervisor
Dan Guy, Price

ARCO Coal Comp
Permits and Compliance Group
555 Seventeenth Street
Mailing Address: Box 5300
Denver, Colorado 80217
Telephone 303 575 7500

*Send a letter establishing full copy fill
10:30 AM 1/13/82 for NOV- fill.
an A.C. Also copy the
Proposed Assessment
to me. (C.V. Spivey I think)
Rm 12/31/81*



NOV 02 1981

DIVISION OF
OIL, GAS & MINING

*cc the letter to
Dan Guy
in Price.*

October 29, 1981

Mr. Ronald W. Daniels
Acting Assessment Officer
Utah Department of Natural Resources
Division of Oil, Gas and Mining
1588 West North Temple
Salt Lake City, Utah 84116

Re: Request for Assessment Conference for DOGM NOV No. N81-4-2-1

Dear Mr. Daniels:

Beaver Creek Coal Company hereby requests an Assessment Conference to review the merits of Item 4 under "Portion of the Operation to Which Notice Applies" and also to discuss the points assessment.


Beaver Creek Coal Company questions the existence of a non-compliance regarding the drainage pattern north and west of the truck dump. It is our understanding of Parts UMC 817.42-.45 that an operators responsibility is to prevent disturbed area runoff from comingling with undisturbed runoff and to convey disturbed runoff in a non-erosive manner to sedimentation ponds for treatment. We contend this was in fact being done in this instance. We also wish to discuss the legality of small impoundments which occupy minor depressions within the disturbed permit area. This has been the subject of discussion on this and previous inspections.

Beaver Creek Coal Company had completed most abatement measures within 24 hours and the remaining work within 48 hours of the inspector noting the problem. We believe this effort of good faith should be reflected in the penalty assessment.

Mr. Ronald W. Daniels
October 29, 1981
Page 2

Please feel free to contact me at (303) 575-7548 or Dan Guy at (801) 637-5050 should you have any questions regarding the NOV or the scheduling of a conference.

Sincerely,

A handwritten signature in cursive script, appearing to read "Ken W. Wangerud", is written over a long horizontal line that extends across the page.

Ken W. Wangerud
Coordinator
Permits and Compliance

cc: D. Guy/BCCC
D. Meyer/BCCC
B. Costello/DLT 1116

KWW/blh