

0007

Document Information Form

Mine Number: C/007/022

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: September 26, 1983

Explanation:

Inspection Memo

cc:

File in: C/007, 022, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

September 26, 1983

Inspection Memo
to Coal File:

RE: Beaver Creek Coal Company
C. V. Spur
ACT/007/022, Folder No. 7
Carbon County, Utah

DATE: August 11, 1983
TIME: 12:30 p.m. - 3:30 p.m.
WEATHER: Clear
COMPANY OFFICIAL: Dan Guy
STATE OFFICIAL: Barton Kale
ENFORCEMENT ACTION: Termination of NOV N83-6-7-1

Compliance With Permanent Program Performance Standards

UMC 771 et al Permits

Tentative approval signed by Jim Smith of the Division is dated December 11, 1981.

A letter dated January 21, 1983 from the Division gives approval for the emergency coal stockpile modification.

A letter dated March 15, 1983 from the Division gives approval of loading system structure for raw coal storage area.

UMC 817.11 Signs and Markers

The entrance sign was posted as required with all pertinent information listed. Perimeter markers were sighted along the boundary on all sides.

UMC 817.21-.25 Topsoil

The topsoil stockpile is separate from the subsoil stockpile. It was noted that growth on the subsoil pile was better than that of the topsoil.

UMC 817.41-.57 Hydrologic Balance

The level of the sediment ponds have all dropped due to correction of the preparation plant water problem. Sediment pond #6 is below the discharge level and, therefore, NOV N83-6-7-1 was terminated. It should be noted that Beaver Creek Coal Company is still responsible for maintaining its storm runoff capacity.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No. 0007 Date 9-26-83
In CI 007, 022, Internal
For additional information _____

INSPECTION MEMO TO COAL FILE
ACT/007/022
September 26, 1983
Page 2


No runoff problems were noted, while berms and ditches seemed to be operational.

UMC 817.52 Hydrologic Balance: Monitoring

C. V. Spur NPDES permit, #UT-0023949, has an expiration date of December 31, 1986. The receiving water is the Price River. No water problems were noted at this time.

UMC 817.81-.93 Coal Processing Waste

The preparation plant waste water ponds have been cleaned recently. The sediment is sent back through the preparation plant. This action has increased the capacity of each of these ponds in series.


BARTON KALE
FIELD SPECIALIST

BK/btb

cc: Tom Ehmett, OSM
Dan Guy, Beaver Creek Coal Company
J. Helfrich, DOGM
J. Whitehead, DOGM

Statistics:

See Gordon Creek #2 Mine memo dated August 18, 1983
Grant: I & E