

0017



SCOTT M. MATHESON
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS, AND MINING
1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

CHARLES R. HENDERSON
Chairman

CLEON B. FEIGHT
Director

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
MAXILIAN A. FARBMAN
EDWARD T. BECK
E. STEELE McINTYRE

Vacation or Termination of Notice or Order

To the Following Permittee or Operator:

Name Beaver Creek Coal Company
Mailing Address PO Box 1378 Price Utah 84501
State Permit No. Ad 1007/022

Utah Coal Mining and Reclamation Act, Section 40-10-1 et. seq., Utah Code Annotated (1953):

Notice of Violation No. N 85-8-4-1 Y TV dated 2/26, 19 85

Cessation Order No. C _____ Y TV dated _____, 19 _____

Violation No. 1 is hereby ✓ Terminated _____ Vacated because:

Violation No. _____ is hereby _____ Terminated _____ Vacated because:

Violation No. _____ is hereby _____ Terminated _____ Vacated because:

Date of Service 2/27/85 Thomas W Wright
Signature of Authorized Representative

Time of Service or Mailing 345 a.m. ✓ p.m. Thomas W Wright #8
Name and I.D. No.



STATE OF UTAH

Notice of Violation No. N 85-8-4-1

Violation No. 1 of 1

Nature of the Violation

failure to conduct surface mining activities under permits issued by the regulatory program complying with terms of the permit and requirements of the Act this chapter and the regulatory program

Provision(s) of the Regulations, Act, or Permit Violated

UMC 77119

Portion of the Operation to which Notice Applies

Undisturbed drainage bypass ditch, north side of site
Disturbed drainage control ditch northwest side of site

Remedial Action Required (including interim steps, if any)

Reestablish drainage controls as approved in the mine plan

Time for Abatement (including time for interim steps, if any)

Two days or no later than 2/28/85