

File *John*

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: June 29, 1987
10:00 a.m. to 2:00 p.m.

Permittee and/or Operators Name: Beaver Creek Coal Co.
Business Address: P.O. Box 1378 Price, Utah 84501
Mine Name: C.V. Spur (prep plant/loadout) Permit Number: ACT/007/022
Type of Mining Activity: Underground Surface Other X
County: Carbon
Company Official (s): Dan Guy
State Official(s): Bill Malencik
Partial: X Complete: Date of Last Inspection: 5/13/87
Weather Conditions: Cloudy/Cool
Acreage: Permitted 160 Disturbed 110 Regraded 0 Seeded 0 Bonded 110
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	(X)	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	(X)	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION June 29, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

RECORDS: Required records were reviewed and found to be in proper order with no problems on the information contained therein. Since the end of the quarter is a day away, not all the second quarter required reports were yet filed.

Maintenance work was underway on the following items:

4b. DIVERSIONS: Ditches were being cleaned and material disposed of according to plan.

4c. SEDIMENT PONDS: Sediment pond no. 5 was partially cleaned and now requires a backhoe to complete the job.

13. REVEGETATION: Revegetation of a small area adjacent to the pumphouse had been completed as covered in previous inspection. Seed germination had taken place in a uniform manner; seedlings primarily of a nurse crop reached a height of about three inches with sparse emergence of grass and other long lived species. All now show drought stress.

Copy of this Report:

Mailed to: Dan Guy, BCCC; Donna Griffin, OSM

Given to: Joe Helfrich

Inspectors Signature and Number: *J. Malencik for*
Bill Malencik #26

Date: July 2, 1987