

0014



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

August 1, 1988

TO: John Whitehead, Permit Supervisor

FROM: James R. Fricke, Reclamation Hydrologist *JRF*

RE: Second Review of 1987 Annual Reports, Beaver Creek Coal Company, C. V. Spur Loadout, ACT/007/022; Gordon Creek #3 and 6 Mine, INA/007/017; Gordon Creek #2 and 7 Mine, ACT/007/016; Trail Mountain #9 Mine, ACT/015/009; Folder No. 2 and #6, Carbon County, Utah

## Synopsis

On May 27, 1988, the Division requested Beaver Creek Coal Company (BCCC) to submit complete water monitoring data for the above mentioned properties. The complete data was to be submitted to the Division on June 20, 1988. On July 27, 1988, BCCC submitted data for Gordon Creek #3 and 6 Mine, and Gordon Creek #2 and 7 Mine. Data was not submitted for C. V. Spur Loadout (precipitation data) and Trail Mountain #9 Mine (field data). Field data deficiencies exist at Gordon Creek #2 and 7 Mine for Stations 2-2-W, 2-3-W, and 2-4-W.

## Recommendations

BCCC monitoring records should be reviewed during each complete inspection for adequacy according to the approved plan and the Division's Water Monitoring Guidelines (1986). Discrepancies should be corrected as soon as possible.

djh  
cc: B. Malencik  
B. Warmack  
0798R/51