

# WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

---

August 26, 2009

TO: Internal File

THRU: Jim Smith, Permit Supervisor *J.S. 08/27/09*

FROM: April A. Abate, Environmental Scientist II/Hydrologist *(CAA) 8-26-2009*

RE: 2009, 2nd Quarter Water Monitoring, Savage Services Corporation, Savage Coal Terminal, C/007/0022 Task #3321

The Savage Coal Terminal is an operating coal loadout where coal is crushed, screened, blended, and then loaded onto rail transport. The operation was restarted in 2006 after several years of being in cessation.

Pertinent water monitoring requirement information is in the MRP in Sections 7.1.6, and 7.2.6, and Figure 7-15.

1. Was data submitted for all of the MRP required sites? YES  NO

**Springs** –

The Permittee is not required to monitor any springs at the Savage Coal Terminal. There are no springs to monitor.

**Streams** –

The Permittee is required to sample CV-14-W, for the parameters outlined in Figure 7-15 in the second and fourth quarter of each year.

Site CV-14-W was monitored this quarter.

**Wells**–

The Permittee is required to sample CV-1-W for the parameters outlined in Figure 7-15 in the second and fourth quarter of each year. S-1-GW and S-2-GW are monitored quarterly. Beginning in 2010, they will be monitored during the second and fourth quarter only.

Sites CV-1-W, S-1-GW and S-2-GW were monitored this quarter. Monitoring

well S-1-GW was dry.

**UPDES**

There is one active UPDES outfall at the Savage Coal Terminal, CV-15-W, or UTG040005-001. The Permittee is required to monitor this UPDES site monthly under Permit # UTG040005 that is due to expire on April 13, 2013.

The location was monitored each month during the 2nd quarter. Permittee recorded no flow at the UPDES point during the period.

**2. Were all required parameters reported for each site?            YES [X] NO [ ]**

**3. Were any irregularities found in the data?                        YES [ ] NO [X]**

**4. On what date does the MRP require a five-year re-sampling of baseline water data.**

The permit renewal was issued on August 6, 2009. Currently there is no specified baseline sampling protocol established for the groundwater monitoring wells.

**5. Based on your review, what further actions, if any, do you recommend?**

None