



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Outgoing
C0070022
3892
OK

August 31, 2011

Garth Nielsen, General Manager
Savage Services Corporation
6340 South 3000 East, Suite 600
Salt Lake City, Utah 84121

Subject: Relocation of Truck Dump and Culverts, Savage Services Corporation, Savage Coal Terminal, C/007/0022, Task # 3892

Dear Mr. Nielsen:

The Division has reviewed your application to relocate the truck dump and select culverts on the permit area.

The Division has determined that there are some deficiencies that must be addressed before a determination can be made that the requirements of the R645 Coal Mining Rules have been met, and an approval can be granted. Those deficiencies are listed as an attachment to this letter.

Each deficiency identifies its author by that author's initials in parentheses, such that your staff can directly communicate with that individual should any questions arise relative to the preparation of Canyon Fuel Company's response to that particular deficiency.

The plans as submitted are denied. Please resubmit the entire application.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/AAA/sqs
Attachment
cc: Price Field Office
O:\007022.SAV\WG3892\3892DEFICIENCIES.DOC



Deficiency List

Task No. 3892

Task Name Relocation of Truck Dump and Culverts

The members of the review team include the following individuals:

April A. Abate (AAA)

[R645-301.512.100 & 722.500]: Please update Figures 5-2 and 7-2 to adequately represent the existing surface configuration and topographic elevation of the refuse pile. Maps should depict the realigned diversion ditch CD-13 and a more accurate representation of the topographic elevation and contours of the refuse pile.

[R645-301-741]: Please update Table 7-26 to reflect that CD-22 has been removed and make any necessary updates to the design specifications of CD-13 on the table based on the realignment of this ditch.