

0014



Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

file

August 10, 1988

TO: John Whitehead, Permit Supervisor
FROM: Pamela Grubaugh-Littig, Reclamation Engineer *pgl*
RE: Completeness Issues, Andalex Resources, Wildcat Loadout,
PRO/007/033, Folder #2, Carbon County, Utah

UMC 783.24 Maps: General Requirements - (PGL)

Plate 1 has been revised and the permit area changed. However, some of the bonded areas are located outside of the permit area. All disturbed (or bonded) areas must lie inside the boundaries of the permit area. Please revise the permit area accordingly. (This comment also applies to UMC 784.23(b)(2) and (b)(3), and UMC 784.24).

UMC 784.16 Reclamation Plan: Ponds, Impoundments, Banks, Dams and Embankments - (PGL)

(a)(1)(7) Certification of all the ponds in Appendix H now state that the constructed ponds "meet the required performance standards outlined in UMC 817.46." Pond E as constructed, however, is not adequate and the proposed design changes are included in the PAP on page 94 and on Plate 6. Please revise the certification for Pond E accordingly.

djh
WP+3