

0012



Utah!

Where ideas connect

Department of Environmental Quality Division of Water Quality

Michael O. Leavitt
Governor
Dianne R. Nielson, Ph.D.
Executive Director
Don A. Ostler, P.E.
Director

288 North 1460 West
P.O. Box 144870
Salt Lake City, Utah 84114-4870
(801) 538-6146
(801) 538-6016 Fax
(801) 536-4414 T.D.D.
www.deq.utah.gov

Water Quality Board
K.C. Shaw, P.E.
Chairman
William R. Williams
Vice-Chairman
Robert G. Adams
Nan Bunker
Ray M. Child, C.P.A.
Neil K. Kochenour, M.D.
Dianne R. Nielson, Ph.D.
Ronald Sims, Ph.D.
Douglas E. Thompson, Mayor
J. Ann Wechsler
Don A. Ostler, P.E.
Executive Secretary

October 28, 2002

Mr. Mike Glasson, Manager of Operations
Andalex Wildcat Loadout
P. O. Box 902
Price, Utah 84501

*Fax PFO
OK
Jacking
2/007/033*

Dear Mike:

Subject: Reconnaissance Inspection of Andalex Wildcat Loadout – Permit UTG040007

On September 18, 2002 I completed a Reconnaissance Inspection of Andalex Wildcat Loadout. No deficiencies were observed, however, it was noted that several of the ponds needed to be cleaned. Mr. Dimick indicated the ponds would be cleaned this spring (001 looked good but 002-006 needed cleaning), There was no discharge at any of the outfalls.

No response is required by Andalex, but if you have any questions please give me a call at (801) 538-6058.

Sincerely,

Michael D. Herkimer, Environmental Scientist
Permits & Compliance Section

MDH:st

Enclosure

cc: Donna Inman, EPA Region VIII, (w/encl)
Claron Bjork, Southeastern Utah District Health Dept., (W/encl)
T David Ariotti, DEQ District Engineer, (w/encl)
Pam Grubaugh Littig, DOGM

Wq/permits/mherkimer/wp/andalexwildcateins.ltr

RECEIVED

OCT 30 2002

DIV. OF OIL, GAS & MINING

