

0015

**From:** Dana Dean  
**To:** Mike Glasson  
**Date:** 8/18/2006 2:02:33 PM  
**Subject:** Re: 2nd Quarter Water Monitoring Data

outgoing  
C0070019 - 2602 JK  
cc: C0070033 - 2603

Mike,

Yes, it does, thank you for responding so quickly. I have included a note with that sample indicating that there was negligible flow and not enough water to perform lab analyses.

It now seems like you have included all required samples and parameters for Centennial and Wildcat for the second quarter of 2006. This will be verified by the assigned hydrologist, you may want to verify for yourself first to avoid having delinquent data. If you do not know how to check the data in the database, please let me know and I can send you instructions.

Please let me know if you have any questions.

Thank you,

Dana Dean, P.E.  
Senior Reclamation Hydrologist  
Utah Division of Oil, Gas, and Mining  
(801) 538-5320  
danadean@utah.gov

>>> "Mike Glasson" <mglasson@UtahAmerican.com> 8/18/2006 11:41 AM >>>

Dana,

Regarding Tower (C 007/019) 2nd quarter water monitoring, I am informed by Karla Knoop that 2nd quarter flow was negligible at site S25-1. The field parameters were measured and reported from a pocket of water at the site, but there was insufficient flow to collect a sample.

I hope this addresses the question adequately

Mike

**CC:** Jim Smith; Karl Houskeeper; Pete Hess; Steve Christensen