

0017



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

**Division of Oil Gas and Mining**

JOHN R. BAZA  
Division Director

Handwritten initials, possibly "JK", in the top right corner.

June 27, 2007

Dave Shaver, Manager  
Andalex Resources  
6750 Airport Road  
P.O. Box 1077  
Price, Utah 84501

Subject: 2006 Midterm Permit Review, Andalex Resources, Inc., Wildcat Loadout, C/007/0033,  
Task ID #2691

Dear Mr. Shaver:

The Division has completed the initial Midterm Permit Review for the Wildcat Loadout. The Division has identified a deficiency that must be addressed satisfactorily before the Division can find that the requirements of the R645 Coal Mining Rules have been met.

That deficiency is described in the attachment to this letter. The deficiency was identified by Wayne H. Western. His phone number is (801) 538-6263. Your staff can directly communicate with Mr. Western relative to the preparation of Andalex Resources, Inc.'s response to this particular deficiency.

Please respond to this deficiency as soon as possible, but no later than July 30, 2007, so that we may efficiently complete this midterm permit review.

Sincerely

Handwritten signature of Pam Grubaugh-Littig in cursive script.

Pam Grubaugh-Littig  
Permit Supervisor

Attachment  
O:\007033.WCL\FINAL\WG2691\DEF2691.DOC

**Deficiency List  
Task No. 2691  
Wildcat Loadout  
2006 Midterm Permit Review**

**R645-301-830.200**, The Permittee must post a minimum bond of \$1,144,000 and include the Division's reclamation cost estimate in the MRP. The Division will provide the Permittee with either a paper or electronic copy of the reclamation cost estimate. [WHW]